










CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (79) / (165) Pages



ANT0_802.11a_UNII 2C






ANT0_802.11a_UNII 3






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (80) / (165) Pages



ANTO_802.11n_HT20_UNII 1







ANTO_802.11n_HT20_UNII 2A






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (81) / (165) Pages



ANTO_802.11n_HT20_UNII 2C






ANTO_802.11n_HT20_UNII 3






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (82) / (165) Pages



ANT1_802.11n_HT20_UNII 1







ANT1_802.11n_HT20_UNII 2A






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (83) / (165) Pages



ANT1_802.11n_HT20_UNII 2C



ANT1_802.11n_HT20_UNII 3