









# CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,  
Gyeonggi-do, Korea  
Tel: +82-1551-9871  
Fax: +82-31-624-9501

REPORT No.:  
CTK-2026-01751  
Page (84) / (165) Pages



## ANT0\_802.11ac\_VHT20\_UNII 1





## ANT0\_802.11ac\_VHT20\_UNII 2A






# CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,  
Gyeonggi-do, Korea  
Tel: +82-1551-9871  
Fax: +82-31-624-9501

REPORT No.:  
CTK-2026-01751  
Page (85) / (165) Pages



## ANT0\_802.11ac\_VHT20\_UNII 2C






## ANT0\_802.11ac\_VHT20\_UNII 3






# CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,  
Gyeonggi-do, Korea  
Tel: +82-1551-9871  
Fax: +82-31-624-9501

REPORT No.:  
CTK-2026-01751  
Page (86) / (165) Pages



## ANT1\_802.11ac\_VHT20\_UNII 1







## ANT1\_802.11ac\_VHT20\_UNII 2A






# CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,  
Gyeonggi-do, Korea  
Tel: +82-1551-9871  
Fax: +82-31-624-9501

REPORT No.:  
CTK-2026-01751  
Page (87) / (165) Pages



## ANT1\_802.11ac\_VHT20\_UNII 2C





## ANT1\_802.11ac\_VHT20\_UNII 3





# CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,  
Gyeonggi-do, Korea  
Tel: +82-1551-9871  
Fax: +82-31-624-9501





REPORT No.:  
CTK-2026-01751  
Page (88) / (165) Pages



## ANT0\_802.11n\_HT40\_UNII 1



## ANT0\_802.11n\_HT40\_UNII 2A



## ANT0\_802.11n\_HT40\_UNII 2C