





CTK Co., Ltd.
(Ho-dong), 113, Yejjik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (89) / (165) Pages





ANT0_802.11n_HT40_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-01751
Page (90) / (165) Pages



ANT1_802.11n_HT40_UNII 1



ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (91) / (165) Pages





ANT1_802.11n_HT40_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-01751
Page (92) / (165) Pages



ANT0_802.11ac_VHT40_UNII 1



ANT0_802.11ac_VHT40_UNII 2A





ANT0_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (93) / (165) Pages





ANT0_802.11ac_VHT40_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-01751
Page (94) / (165) Pages



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (95) / (165) Pages



ANT1_802.11ac_VHT40_UNII 3