










CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (28) / (165) Pages



ANT1_802.11n_HT20_UNI1 2C






ANT1_802.11n_HT20_UNI1 3






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (29) / (165) Pages



ANT0_802.11ac_VHT20_UNII 1







ANT0_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (30) / (165) Pages



ANT0_802.11ac_VHT20_UNII 2C






ANT0_802.11ac_VHT20_UNII 3






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (31) / (165) Pages



ANT1_802.11ac_VHT20_UNII 1



ANT1_802.11ac_VHT20_UNII 2A