







CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-01751
Page (61) / (165) Pages





ANT0_802.11n_HT40_UNII 1



ANT0_802.11n_HT40_UNII 2A



ANT0_802.11n_HT40_UNII 2C





ANT0_802.11n_HT40_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-01751
Page (63) / (165) Pages



ANT1_802.11n_HT40_UNII 1



ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (64) / (165) Pages





ANT1_802.11n_HT40_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-01751
Page (65) / (165) Pages



ANT0_802.11ac_VHT40_UNI1



ANT0_802.11ac_VHT40_UNI1 2A





ANT0_802.11ac_VHT40_UNI1 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-1551-9871
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-01751
Page (66) / (165) Pages



ANT0_802.11ac_VHT40_UNII 3