



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (259) / (417) Pages



ANT1_802.11ax_HE80_26T_Low_UNII 5





ANT1_802.11ax_HE80_26T_Low_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (260) / (417) Pages



ANT1_802.11ax_HE80_26T_Low_UNII 7






ANT1_802.11ax_HE80_26T_Low_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (261) / (417) Pages



ANT0_802.11ax_HE80_26T_Mid_UNII 5






ANT0_802.11ax_HE80_26T_Mid_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (262) / (417) Pages



ANT0_802.11ax_HE80_26T_Mid_UNII 7




ANT0_802.11ax_HE80_26T_Mid_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (263) / (417) Pages



ANT1_802.11ax_HE80_26T_Mid_UNII 5



ANT1_802.11ax_HE80_26T_Mid_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (264) / (417) Pages



ANT1_802.11ax_HE80_26T_Mid_UNII 7



ANT1_802.11ax_HE80_26T_Mid_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (265) / (417) Pages



ANT0_802.11ax_HE80_26T_High_UNII 5



ANT0_802.11ax_HE80_26T_High_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (266) / (417) Pages



ANTO_802.11ax_HE80_26T_High_UNII 7



ANTO_802.11ax_HE80_26T_High_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (267) / (417) Pages



ANT1_802.11ax_HE80_26T_High_UNII 5



ANT1_802.11ax_HE80_26T_High_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (268) / (417) Pages



ANT1_802.11ax_HE80_26T_High_UNII 7



ANT1_802.11ax_HE80_26T_High_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (269) / (417) Pages



ANT0_802.11ax_HE80_52T_Low_UNII 5




ANT0_802.11ax_HE80_52T_Low_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (270) / (417) Pages



ANT0_802.11ax_HE80_52T_Low_UNII 7



ANT0_802.11ax_HE80_52T_Low_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (271) / (417) Pages



ANT1_802.11ax_HE80_52T_Low_UNII 5





ANT1_802.11ax_HE80_52T_Low_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (272) / (417) Pages



ANT1_802.11ax_HE80_52T_Low_UNII 7






ANT1_802.11ax_HE80_52T_Low_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (273) / (417) Pages



ANT0_802.11ax_HE80_52T_Mid_UNII 5






ANT0_802.11ax_HE80_52T_Mid_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (274) / (417) Pages



ANT0_802.11ax_HE80_52T_Mid_UNII 7






ANT0_802.11ax_HE80_52T_Mid_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (275) / (417) Pages



ANT1_802.11ax_HE80_52T_Mid_UNII 5






ANT1_802.11ax_HE80_52T_Mid_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (276) / (417) Pages



ANT1_802.11ax_HE80_52T_Mid_UNII 7



ANT1_802.11ax_HE80_52T_Mid_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (277) / (417) Pages



ANT0_802.11ax_HE80_52T_High_UNII 5



ANT0_802.11ax_HE80_52T_High_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (278) / (417) Pages



ANTO_802.11ax_HE80_52T_High_UNII 7



ANTO_802.11ax_HE80_52T_High_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (279) / (417) Pages



ANT1_802.11ax_HE80_52T_High_UNII 5



ANT1_802.11ax_HE80_52T_High_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (280) / (417) Pages



ANT1_802.11ax_HE80_52T_High_UNII 7



ANT1_802.11ax_HE80_52T_High_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (281) / (417) Pages



ANT0_802.11ax_HE80_106T_Low_UNII 5



ANT0_802.11ax_HE80_106T_Low_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (282) / (417) Pages



ANT0_802.11ax_HE80_106T_Low_UNII 7






ANT0_802.11ax_HE80_106T_Low_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (283) / (417) Pages



ANT1_802.11ax_HE80_106T_Low_UNII 5






ANT1_802.11ax_HE80_106T_Low_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (284) / (417) Pages



ANT1_802.11ax_HE80_106T_Low_UNII 7





ANT1_802.11ax_HE80_106T_Low_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (285) / (417) Pages



ANT0_802.11ax_HE80_106T_Mid_UNII 5






ANT0_802.11ax_HE80_106T_Mid_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (286) / (417) Pages



ANTO_802.11ax_HE80_106T_Mid_UNII 7






ANTO_802.11ax_HE80_106T_Mid_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (287) / (417) Pages



ANT1_802.11ax_HE80_106T_Mid_UNII 5





ANT1_802.11ax_HE80_106T_Mid_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (288) / (417) Pages



ANT1_802.11ax_HE80_106T_Mid_UNII 7



ANT1_802.11ax_HE80_106T_Mid_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (289) / (417) Pages



ANT0_802.11ax_HE80_106T_High_UNII 5





ANT0_802.11ax_HE80_106T_High_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (290) / (417) Pages



ANT0_802.11ax_HE80_106T_High_UNII 7



ANT0_802.11ax_HE80_106T_High_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (291) / (417) Pages



ANT1_802.11ax_HE80_106T_High_UNII 5



ANT1_802.11ax_HE80_106T_High_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (292) / (417) Pages



ANT1_802.11ax_HE80_106T_High_UNII 7





ANT1_802.11ax_HE80_106T_High_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (293) / (417) Pages



ANT0_802.11ax_HE80_242T_Low_UNII 5





ANT0_802.11ax_HE80_242T_Low_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (294) / (417) Pages



ANT0_802.11ax_HE80_242T_Low_UNII 7




ANT0_802.11ax_HE80_242T_Low_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (295) / (417) Pages



ANT1_802.11ax_HE80_242T_Low_UNII 5





ANT1_802.11ax_HE80_242T_Low_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (296) / (417) Pages



ANT1_802.11ax_HE80_242T_Low_UNII 7






ANT1_802.11ax_HE80_242T_Low_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (297) / (417) Pages



ANT0_802.11ax_HE80_242T_Mid_UNII 5






ANT0_802.11ax_HE80_242T_Mid_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (298) / (417) Pages



ANTO_802.11ax_HE80_242T_Mid_UNII 7





ANTO_802.11ax_HE80_242T_Mid_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (299) / (417) Pages



ANT1_802.11ax_HE80_242T_Mid_UNII 5






ANT1_802.11ax_HE80_242T_Mid_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


REPORT No.:
CTK-2026-00064
Page (300) / (417) Pages



ANT1_802.11ax_HE80_242T_Mid_UNII 7



ANT1_802.11ax_HE80_242T_Mid_UNII 8








CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (301) / (417) Pages



ANT0_802.11ax_HE80_242T_High_UNII 5






ANT0_802.11ax_HE80_242T_High_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (302) / (417) Pages



ANT0_802.11ax_HE80_242T_High_UNII 7




ANT0_802.11ax_HE80_242T_High_UNII 8



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (303) / (417) Pages



ANT1_802.11ax_HE80_242T_High_UNII 5




ANT1_802.11ax_HE80_242T_High_UNII 6



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (304) / (417) Pages



ANT1_802.11ax_HE80_242T_High_UNII 7






ANT1_802.11ax_HE80_242T_High_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (305) / (417) Pages



ANT0_802.11ax_HE80_484T_Low_UNII 5






ANT0_802.11ax_HE80_484T_Low_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (306) / (417) Pages



ANT0_802.11ax_HE80_484T_Low_UNII 7






ANT0_802.11ax_HE80_484T_Low_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (307) / (417) Pages



ANT1_802.11ax_HE80_484T_Low_UNII 5






ANT1_802.11ax_HE80_484T_Low_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (308) / (417) Pages



ANT1_802.11ax_HE80_484T_Low_UNII 7






ANT1_802.11ax_HE80_484T_Low_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (309) / (417) Pages



ANT0_802.11ax_HE80_484T_High_UNII 5





ANT0_802.11ax_HE80_484T_High_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00064
Page (310) / (417) Pages



ANT0_802.11ax_HE80_484T_High_UNII 7



ANT0_802.11ax_HE80_484T_High_UNII 8