






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (58) / (534) Pages



ANT1_802.11n_HT20_UNII 1



ANT1_802.11n_HT20_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (59) / (534) Pages



ANT1_802.11n_HT20_UNII 2C



ANT1_802.11n_HT20_UNII 3






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (60) / (534) Pages



ANT0_802.11ac_VHT20_UNII 1




ANT0_802.11ac_VHT20_UNII 2A




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (61) / (534) Pages



ANT0_802.11ac_VHT20_UNII 2C




ANT0_802.11ac_VHT20_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (62) / (534) Pages



ANT1_802.11ac_VHT20_UNII 1



ANT1_802.11ac_VHT20_UNII 2A




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (63) / (534) Pages



ANT1_802.11ac_VHT20_UNII 2C





ANT1_802.11ac_VHT20_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (64) / (534) Pages



ANT0_802.11ax_HE20_26T_Low_UNII 1





ANT0_802.11ax_HE20_26T_Low_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (65) / (534) Pages



ANT0_802.11ax_HE20_26T_Low_UNII 2C




ANT0_802.11ax_HE20_26T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-00063
Page (66) / (534) Pages




ANT1_802.11ax_HE20_26T_Low_UNII 1



ANT1_802.11ax_HE20_26T_Low_UNII 2A



ANT1_802.11ax_HE20_26T_Low_UNII 2C




ANT1_802.11ax_HE20_26T_Low_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (68) / (534) Pages



ANT0 802.11ax_HE20_26T Mid UNII 1




ANT0_802.11ax_HE20_26T_Mid_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (69) / (534) Pages



ANTO_802.11ax_HE20_26T_Mid_UNII 2C




ANTO_802.11ax_HE20_26T_Mid_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (70) / (534) Pages



ANT1_802.11ax_HE20_26T_Mid_UNI1 1




ANT1_802.11ax_HE20_26T_Mid_UNI1 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (71) / (534) Pages



ANT1_802.11ax_HE20_26T_Mid_UNII 2C




ANT1_802.11ax_HE20_26T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (72) / (534) Pages



ANT0_802.11ax_HE20_26T_High_UNII 1





ANT0_802.11ax_HE20_26T_High_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (73) / (534) Pages



ANT0_802.11ax_HE20_26T_High_UNII 2C




ANT0_802.11ax_HE20_26T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (74) / (534) Pages



ANT1_802.11ax_HE20_26T_High_UNII 1



ANT1_802.11ax_HE20_26T_High_UNII 2A




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (75) / (534) Pages



ANT1_802.11ax_HE20_26T_High_UNII 2C





ANT1_802.11ax_HE20_26T_High_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (76) / (534) Pages



ANT0_802.11ax_HE20_242T_UNII 1







ANT0_802.11ax_HE20_242T_UNII 1A






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (77) / (534) Pages



ANT0_802.11ax_HE20_242T_UNII 2C






ANT0_802.11ax_HE20_242T_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (78) / (534) Pages



ANT1_802.11ax_HE20_242T_UNII 1





ANT1_802.11ax_HE20_242T_UNII 2A





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (79) / (534) Pages



ANT1_802.11ax_HE20_242T_UNII 2C





ANT1_802.11ax_HE20_242T_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



REPORT No.:
CTK-2026-00063
Page (80) / (534) Pages



ANT0_802.11n_HT40_UNII 1



ANT0_802.11n_HT40_UNII 2A





ANT0_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (81) / (534) Pages



ANT0_802.11n_HT40_U1I 3




ANT1_802.11n_HT40_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



REPORT No.:
CTK-2026-00063
Page (84) / (534) Pages



ANT0_802.11ac_VHT40_UNI 1



ANT0_802.11ac_VHT40_UNI 2A





ANT0_802.11ac_VHT40_UNI 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (85) / (534) Pages





ANT0_802.11ac_VHT40_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



REPORT No.:
CTK-2026-00063
Page (86) / (534) Pages



ANT1_802.11ac_VHT40_UNI 1



ANT1_802.11ac_VHT40_UNI 2A




ANT1_802.11ac_VHT40_UNI 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (87) / (534) Pages




ANT1_802.11ac_VHT40_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-00063
Page (88) / (534) Pages



ANT0_802.11ax_HE40_26T_Low_UNII 1



ANT0_802.11ax_HE40_26T_Low_UNII 2A





ANT0_802.11ax_HE40_26T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (89) / (534) Pages





ANT0_802.11ax_HE40_26T_Low_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-00063
Page (90) / (534) Pages



ANT1_802.11ax_HE40_26T_Low_UNII 1



ANT1_802.11ax_HE40_26T_Low_UNII 2A





ANT1_802.11ax_HE40_26T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (91) / (534) Pages



ANT1_802.11ax_HE40_26T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




REPORT No.:
CTK-2026-00063
Page (92) / (534) Pages



ANT0_802.11ax_HE40_26T_Mid_UNII 1



ANT0_802.11ax_HE40_26T_Mid_UNII 2A



ANT0_802.11ax_HE40_26T_Mid_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (93) / (534) Pages



ANT0_802.11ax_HE40_26T_Mid_UNI1 3