




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (241) / (534) Pages



ANT0_802.11ax_HE20_52T_Low_UNII 2C



ANT0_802.11ax_HE20_52T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (242) / (534) Pages



ANT1_802.11ax_HE20_52T_Low_UNII 1



ANT1_802.11ax_HE20_52T_Low_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (243) / (534) Pages



ANT1_802.11ax_HE20_52T_Low_UNI 2C



ANT1_802.11ax_HE20_52T_Low_UNI 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (244) / (534) Pages



ANT0_802.11ax_HE20_52T_Mid_UNII 1





ANT0_802.11ax_HE20_52T_Mid_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (245) / (534) Pages



ANT0_802.11ax_HE20_52T_Mid_UNII 2C




ANT0_802.11ax_HE20_52T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (246) / (534) Pages



ANT1_802.11ax_HE20_52T_Mid_UNII 1




ANT1_802.11ax_HE20_52T_Mid_UNII 2A




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (247) / (534) Pages



ANT1_802.11ax_HE20_52T_Mid_UNII 2C



ANT1_802.11ax_HE20_52T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (248) / (534) Pages



ANT0_802.11ax_HE20_52T_High_UNII 1




ANT0_802.11ax_HE20_52T_High_UNII 2A




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (249) / (534) Pages



ANT0_802.11ax_HE20_52T_High_UNII 2C




ANT0_802.11ax_HE20_52T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (250) / (534) Pages



ANT1_802.11ax_HE20_52T_High_UNII 1





ANT1_802.11ax_HE20_52T_High_UNII 2A




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (251) / (534) Pages



ANT1_802.11ax_HE20_52T_High_UNII 2C



ANT1_802.11ax_HE20_52T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (252) / (534) Pages



ANT0_802.11ax_HE20_106T_Low_UNII 1




ANT0_802.11ax_HE20_106T_Low_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (253) / (534) Pages



ANT0_802.11ax_HE20_106T_Low_UNII 2C



ANT0_802.11ax_HE20_106T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (254) / (534) Pages



ANT1_802.11ax_HE20_106T_Low_UNII 1





ANT1_802.11ax_HE20_106T_Low_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (255) / (534) Pages



ANT1_802.11ax_HE20_106T_Low_UNII 2C



ANT1_802.11ax_HE20_106T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (256) / (534) Pages



ANT0_802.11ax_HE20_106T_High_UNII 1



ANT0_802.11ax_HE20_106T_High_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (257) / (534) Pages



ANT0_802.11ax_HE20_106T_High_UNII 2C



ANT0_802.11ax_HE20_106T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (258) / (534) Pages



ANT1_802.11ax_HE20_106T_High_UNII 1



ANT1_802.11ax_HE20_106T_High_UNII 2A





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (259) / (534) Pages



ANT1_802.11ax_HE20_106T_High_UNII 2C




ANT1_802.11ax_HE20_106T_High_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (260) / (534) Pages



ANT0_802.11ax_HE20_242T_UNII 1





ANT0_802.11ax_HE20_242T_UNII 2A




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (261) / (534) Pages



ANT0_802.11ax_HE20_242T_UNII 2C



ANT0_802.11ax_HE20_242T_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (262) / (534) Pages



ANT1_802.11ax_HE20_242T_UNII 1





ANT1_802.11ax_HE20_242T_UNII 2A



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (263) / (534) Pages



ANT1_802.11ax_HE20_242T_UNII 2C



ANT1_802.11ax_HE20_242T_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (264) / (534) Pages



ANT0_802.11n_HT40_UNII 1



ANT0_802.11n_HT40_UNII 2A



ANT0_802.11n_HT40_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (265) / (534) Pages



ANT0_802.11n_HT40_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (266) / (534) Pages



ANT1_802.11n_HT40_UNII 2A



ANT1_802.11n_HT40_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (267) / (534) Pages



ANT1_802.11n_HT40_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (268) / (534) Pages



ANT0_802.11ac_VHT40_UNII 1



ANT0_802.11ac_VHT40_UNII 2A



ANT0_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (269) / (534) Pages



ANT0_802.11ac_VHT40_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (270) / (534) Pages



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A



ANT1_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (271) / (534) Pages



ANT1_802.11ac_VHT40_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (272) / (534) Pages



ANT0_802.11ax_HE40_26T_Low_UNII 1



ANT0_802.11ax_HE40_26T_Low_UNII 2A



ANT0_802.11ax_HE40_26T_Low_UNII 2C





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (273) / (534) Pages



ANT0_802.11ax_HE40_26T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (274) / (534) Pages



ANT1_802.11ax_HE40_26T_Low_UNII 1



ANT1_802.11ax_HE40_26T_Low_UNII 2A



ANT1_802.11ax_HE40_26T_Low_UNII 2C





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (275) / (534) Pages



ANT1_802.11ax_HE40_26T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (276) / (534) Pages



ANTO_802.11ax_HE40_26T_Mid_UNII 1



ANTO_802.11ax_HE40_26T_Mid_UNII 2A



ANTO_802.11ax_HE40_26T_Mid_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (277) / (534) Pages



ANT0_802.11ax_HE40_26T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (278) / (534) Pages



ANT1_802.11ax_HE40_26T_Mid_UNII 1



ANT1_802.11ax_HE40_26T_Mid_UNII 2A



ANT1_802.11ax_HE40_26T_Mid_UNII 2C





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (279) / (534) Pages



ANT1_802.11ax_HE40_26T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (280) / (534) Pages



ANT0_802.11ax_HE40_26T_High_UNII 1



ANT0_802.11ax_HE40_26T_High_UNII 2A



ANT0_802.11ax_HE40_26T_High_UNII 2C