



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (281) / (534) Pages



ANT0_802.11ax_HE40_26T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (282) / (534) Pages



ANT1_802.11ax_HE40_26T_High_UNII 1



ANT1_802.11ax_HE40_26T_High_UNII 2A



ANT1_802.11ax_HE40_26T_High_UNII 2C





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (283) / (534) Pages





ANT1_802.11ax_HE40_26T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (284) / (534) Pages



ANT0_802.11ax_HE40_52T_Low_UNII 1



ANT0_802.11ax_HE40_52T_Low_UNII 2A





ANT0_802.11ax_HE40_52T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (285) / (534) Pages



ANT0_802.11ax_HE40_52T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (286) / (534) Pages



ANT1_802.11ax_HE40_52T_Low_UNII 1



ANT1_802.11ax_HE40_52T_Low_UNII 2A




ANT1_802.11ax_HE40_52T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (287) / (534) Pages




ANT1_802.11ax_HE40_52T_Low_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




REPORT No.:
CTK-2026-00063
Page (288) / (534) Pages



ANTO_802.11ax_HE40_52T_Mid_UNII 1



ANTO_802.11ax_HE40_52T_Mid_UNII 2A





ANTO_802.11ax_HE40_52T_Mid_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (289) / (534) Pages



ANT0_802.11ax_HE40_52T_Mid_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-00063
Page (290) / (534) Pages




ANT1_802.11ax_HE40_52T_Mid_UNII 1



ANT1_802.11ax_HE40_52T_Mid_UNII 2A





ANT1_802.11ax_HE40_52T_Mid_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (291) / (534) Pages



ANT1_802.11ax_HE40_52T_Mid_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (292) / (534) Pages



ANT0_802.11ax_HE40_52T_High_UNII 1



ANT0_802.11ax_HE40_52T_High_UNII 2A



ANT0_802.11ax_HE40_52T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (293) / (534) Pages



ANT0_802.11ax_HE40_52T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (294) / (534) Pages



ANT1_802.11ax_HE40_52T_High_UNII 1



ANT1_802.11ax_HE40_52T_High_UNII 2A



ANT1_802.11ax_HE40_52T_High_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (295) / (534) Pages




ANT1_802.11ax_HE40_52T_High_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (296) / (534) Pages



ANT0_802.11ax_HE40_106T_Low_UNII 1



ANT0_802.11ax_HE40_106T_Low_UNII 2A




ANT0_802.11ax_HE40_106T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (297) / (534) Pages



ANT0_802.11ax_HE40_106T_Low_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (298) / (534) Pages



ANT1_802.11ax_HE40_106T_Low_UNII 1



ANT1_802.11ax_HE40_106T_Low_UNII 2A



ANT1_802.11ax_HE40_106T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (299) / (534) Pages



ANT1_802.11ax_HE40_106T_Low_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



REPORT No.:
CTK-2026-00063
Page (300) / (534) Pages





ANT0_802.11ax_HE40_106T_Mid_UNII 1



ANT0_802.11ax_HE40_106T_Mid_UNII 2A




ANT0_802.11ax_HE40_106T_Mid_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (301) / (534) Pages




ANT0_802.11ax_HE40_106T_Mid_UNII 3



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (303) / (534) Pages




ANT1_802.11ax_HE40_106T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (304) / (534) Pages



ANT0_802.11ax_HE40_106T_High_UNII 1



ANT0_802.11ax_HE40_106T_High_UNII 2A




ANT0_802.11ax_HE40_106T_High_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (305) / (534) Pages



ANT0_802.11ax_HE40_106T_High_UNII 3




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (306) / (534) Pages



ANT1_802.11ax_HE40_106T_High_UNII 1



ANT1_802.11ax_HE40_106T_High_UNII 2A




ANT1_802.11ax_HE40_106T_High_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (307) / (534) Pages




ANT1_802.11ax_HE40_106T_High_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



REPORT No.:
CTK-2026-00063
Page (308) / (534) Pages





ANT0_802.11ax_HE40_242T_Low_UNII 1



ANT0_802.11ax_HE40_242T_Low_UNII 2A




ANT0_802.11ax_HE40_242T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (309) / (534) Pages




ANT0_802.11ax_HE40_242T_Low_UNII 3






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-00063
Page (310) / (534) Pages



ANT1_802.11ax_HE40_242T_Low_UNII 1



ANT1_802.11ax_HE40_242T_Low_UNII 2A





ANT1_802.11ax_HE40_242T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (311) / (534) Pages





ANT1_802.11ax_HE40_242T_Low_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





REPORT No.:
CTK-2026-00063
Page (312) / (534) Pages



ANT0_802.11ax_HE40_242T_High_UNII 1



ANT0_802.11ax_HE40_242T_High_UNII 2A





ANT0_802.11ax_HE40_242T_High_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (313) / (534) Pages





ANT0_802.11ax_HE40_242T_High_UNII 3





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




REPORT No.:
CTK-2026-00063
Page (314) / (534) Pages



ANT1_802.11ax_HE40_242T_High_UNII 1



ANT1_802.11ax_HE40_242T_High_UNII 2A





ANT1_802.11ax_HE40_242T_High_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (315) / (534) Pages



ANT1_802.11ax_HE40_242T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (316) / (534) Pages



ANT0_802.11ax_HE40_484T_UNII 1



ANT0_802.11ax_HE40_484T_UNII 2A



ANT0_802.11ax_HE40_484T_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (317) / (534) Pages



ANT0_802.11ax_HE40_484T_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (318) / (534) Pages



ANT1_802.11ax_HE40_484T_UNII 1



ANT1_802.11ax_HE40_484T_UNII 2A



ANT1_802.11ax_HE40_484T_UNII 2C



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (319) / (534) Pages



ANT1_802.11ax_HE40_484T_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (320) / (534) Pages



ANT0_802.11ac_VHT80_UNII 1



ANT0_802.11ac_VHT80_UNII 2A



ANT0_802.11ac_VHT80_UNII 2C



ANT0_802.11ac_VHT80_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (321) / (534) Pages



ANT1_802.11ac_VHT80_UNII 1



ANT1_802.11ac_VHT80_UNII 2A



ANT1_802.11ac_VHT80_UNII 2C



ANT1_802.11ac_VHT80_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (322) / (534) Pages



ANT0_802.11ax_HE80_26T_Low_UNII 1



ANT0_802.11ax_HE80_26T_Low_UNII 2A



ANT0_802.11ax_HE80_26T_Low_UNII 2C



ANT0_802.11ax_HE80_26T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (323) / (534) Pages



ANT1_802.11ax_HE80_26T_Low_UNII 1



ANT1_802.11ax_HE80_26T_Low_UNII 2A



ANT1_802.11ax_HE80_26T_Low_UNII 2C



ANT1_802.11ax_HE80_26T_Low_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (324) / (534) Pages



ANTO_802.11ax_HE80_26T_Mid_UNII 1



ANTO_802.11ax_HE80_26T_Mid_UNII 2A



ANTO_802.11ax_HE80_26T_Mid_UNII 2C



ANTO_802.11ax_HE80_26T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (325) / (534) Pages



ANT1_802.11ax_HE80_26T_Mid_UNII 1



ANT1_802.11ax_HE80_26T_Mid_UNII 2A



ANT1_802.11ax_HE80_26T_Mid_UNII 2C



ANT1_802.11ax_HE80_26T_Mid_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (326) / (534) Pages



ANT0_802.11ax_HE80_26T_High_UNII 1



ANT0_802.11ax_HE80_26T_High_UNII 2A



ANT0_802.11ax_HE80_26T_High_UNII 2C



ANT0_802.11ax_HE80_26T_High_UNII 3



CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2026-00063
Page (327) / (534) Pages



ANT1_802.11ax_HE80_26T_High_UNII 1



ANT1_802.11ax_HE80_26T_High_UNII 2A



ANT1_802.11ax_HE80_26T_High_UNII 2C



ANT1_802.11ax_HE80_26T_High_UNII 3