


A.1 PHOTOGRAPHS OF MEASUREMENT



Note: 1.EUT: Slave ; 2.Master: AP