










CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (90) / (166) Pages



802.11be_EHT20_SU_UNII 7






802.11be_EHT20_SU_UNII 8





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (91) / (166) Pages



802.11ax_HE40_SU_UNII 5






802.11ax_HE40_SU_UNII 6






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (92) / (166) Pages



802.11ax_HE40_SU_UNII 7






802.11ax_HE40_SU_UNII 8





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (93) / (166) Pages



802.11be_EHT40_SU_UNII 5






802.11be_EHT40_SU_UNII 6






CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (94) / (166) Pages



802.11be_EHT40_SU_UNII 7






802.11be_EHT40_SU_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (95) / (166) Pages



802.11ax HE80_SU_UNII 5






802.11ax_HE80_SU_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (96) / (166) Pages



802.11ax_HE80_SU_UNII 7






802.11ax_HE80_SU_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (97) / (166) Pages



802.11be EHT80 SU_UNII 5






802.11be EHT80_SU_UNII 6





CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (98) / (166) Pages



802.11be_EHT80_SU_UNII 7






802.11be_EHT80_SU_UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (99) / (166) Pages



802.11ax HE160_SU_UNII 5





802.11ax_HE160_SU_UNII 6




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (100) / (166) Pages



802.11ax HE160 SU UNII 7






802.11ax HE160 SU UNII 8




CTK Co., Ltd.

(Ho-dong), 113, Yejik-ro, Cheoin-gu, Yongin-si,
Gyeonggi-do, 17142, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

REPORT No.:
CTK-2025-03707
Page (101) / (166) Pages



802.11be EHT160_SU_UNII 5



802.11be EHT160_SU_UNII 6