






Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT20	Tested By	Kuper Hsu
Frequency	TX 2412MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3




Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT20	Tested By	Kuper Hsu
Frequency	TX 2437MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3




Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT20	Tested By	Kuper Hsu
Frequency	TX 2462MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3







Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT20	Tested By	Kuper Hsu
Frequency	TX 2472MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3




Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT40	Tested By	Kuper Hsu
Frequency	TX 2422MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3



Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT40	Tested By	Kuper Hsu
Frequency	TX 2437MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3




Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT40	Tested By	Kuper Hsu
Frequency	TX 2452MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)		3	



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11n-HT40	Tested By	Kuper Hsu
Frequency	TX 2462MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2019/12/04	Temp./Hum.	20°C/47%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE20	Tested By	Kuper Hsu
Frequency	TX 2412MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3




Test Date	2019/12/04	Temp./Hum.	20°C/47%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE20	Tested By	Kuper Hsu
Frequency	TX 2437MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3



Test Date	2019/12/04	Temp./Hum.	20°C/47%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE20	Tested By	Kuper Hsu
Frequency	TX 2462MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3




Test Date	2019/12/04	Temp./Hum.	20°C/47%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE20	Tested By	Kuper Hsu
Frequency	TX 2472MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3







Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE40	Tested By	Kuper Hsu
Frequency	TX 2422MHz	Chipset	MT7915DUN
Simultaneous Factor	10 log(n) (Note: "n" is antenna number)		3



Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE40	Tested By	Kuper Hsu
Frequency	TX 2437MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3



Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE40	Tested By	Kuper Hsu
Frequency	TX 2452MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)		3	



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2019/12/05	Temp./Hum.	22°C/53%
Cable Loss	0.8dB	Test Voltage	DC 5V (via Test JIG)
Mode	802.11ax-HE40	Tested By	Kuper Hsu
Frequency	TX 2462MHz	Chipset	MT7915DUN
Simultaneous Factor10 log(n) (Note: "n" is antenna number)		3	

