



Freq. Stability 40C 3V ax20 5700MHz Ant2 0 Minutes




Date: 22.MAY.2025 18:07:57

Freq. Stability 50C 3V ax20 5700MHz Ant2 0 Minutes




Date: 22.MAY.2025 18:08:02


Freq. Stability 20C 2.805V ax40 5190MHz Ant1 0 Minutes




Freq. Stability 20C 3.3V ax40 5190MHz Ant1 0 Minutes




Freq. Stability 20C 3.795V ax40 5190MHz Ant1 0 Minutes



Freq. Stability -20C 3V ax40 5190MHz Ant1 0 Minutes




Freq. Stability -10C 3V ax40 5190MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:12:40

Freq. Stability 0C 3V ax40 5190MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:12:51

Freq. Stability 10C 3V ax40 5190MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:13:02

Freq. Stability 20C 3V ax40 5190MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:13:13

Freq. Stability 30C 3V ax40 5190MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:13:24

Freq. Stability 40C 3V ax40 5190MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:13:35

Freq. Stability 50C 3V ax40 5190MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:13:46

Freq. Stability 20C 2.805V ax40 5230MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:05:07


Freq. Stability 20C 3.3V ax40 5230MHz Ant1 0 Minutes




Freq. Stability 20C 3.795V ax40 5230MHz Ant1 0 Minutes




Freq. Stability -20C 3V ax40 5230MHz Ant1 0 Minutes




Freq. Stability -10C 3V ax40 5230MHz Ant1 0 Minutes




Freq. Stability 0C 3V ax40 5230MHz Ant1 0 Minutes



Freq. Stability 10C 3V ax40 5230MHz Ant1 0 Minutes




Freq. Stability 20C 3V ax40 5230MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:06:24

Freq. Stability 30C 3V ax40 5230MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:06:35

Freq. Stability 40C 3V ax40 5230MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:06:46

Freq. Stability 50C 3V ax40 5230MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:06:57


Freq. Stability 20C 2.805V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 20C 3.3V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 20C 3.795V ax40 5270MHz Ant1 0 Minutes




Freq. Stability -20C 3V ax40 5270MHz Ant1 0 Minutes




Freq. Stability -10C 3V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 0C 3V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 10C 3V ax40 5270MHz Ant1 0 Minutes



Freq. Stability 20C 3V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 30C 3V ax40 5270MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:00:25

Freq. Stability 40C 3V ax40 5270MHz Ant1 0 Minutes




Date: 23.MAY.2025 11:00:33


Freq. Stability 50C 3V ax40 5270MHz Ant1 0 Minutes




Freq. Stability 20C 2.805V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 20C 3.3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 20C 3.795V ax40 5310MHz Ant1 0 Minutes




Freq. Stability -20C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability -10C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 0C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 10C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 20C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 30C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 40C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 50C 3V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 20C 2.805V ax40 5510MHz Ant1 0 Minutes




Freq. Stability 20C 3.3V ax40 5510MHz Ant1 0 Minutes




Freq. Stability 20C 3.795V ax40 5510MHz Ant1 0 Minutes




Freq. Stability -20C 3V ax40 5510MHz Ant1 0 Minutes




Freq. Stability -10C 3V ax40 5510MHz Ant1 0 Minutes




Freq. Stability 0C 3V ax40 5510MHz Ant1 0 Minutes




Freq. Stability 10C 3V ax40 5510MHz Ant1 0 Minutes




Freq. Stability 20C 3V ax40 5510MHz Ant1 0 Minutes




Freq. Stability 30C 3V ax40 5510MHz Ant1 0 Minutes



Freq. Stability 40C 3V ax40 5510MHz Ant1 0 Minutes




Freq. Stability 50C 3V ax40 5510MHz Ant1 0 Minutes




Date: 23.MAY.2025 10:47:52

Freq. Stability 20C 2.805V ax40 5590MHz Ant1 0 Minutes




Date: 23.MAY.2025 09:21:21


Freq. Stability 20C 3.3V ax40 5590MHz Ant1 0 Minutes



Freq. Stability 20C 3.795V ax40 5590MHz Ant1 0 Minutes




Freq. Stability -20C 3V ax40 5590MHz Ant1 0 Minutes




Date: 23.MAY.2025 09:21:53

Freq. Stability -10C 3V ax40 5590MHz Ant1 0 Minutes




Date: 23.MAY.2025 09:22:04


Freq. Stability 0C 3V ax40 5590MHz Ant1 0 Minutes




Freq. Stability 10C 3V ax40 5590MHz Ant1 0 Minutes




Freq. Stability 20C 3V ax40 5590MHz Ant1 0 Minutes




Freq. Stability 30C 3V ax40 5590MHz Ant1 0 Minutes




Freq. Stability 40C 3V ax40 5590MHz Ant1 0 Minutes



Freq. Stability 50C 3V ax40 5590MHz Ant1 0 Minutes



Freq. Stability 20C 2.805V ax40 5670MHz Ant1 0 Minutes



Freq. Stability 20C 3.3V ax40 5670MHz Ant1 0 Minutes

