




Freq. Stability 20C 3.795V ax40 5670MHz Ant1 0 Minutes



Freq. Stability -20C 3V ax40 5670MHz Ant1 0 Minutes




Freq. Stability -10C 3V ax40 5670MHz Ant1 0 Minutes




Date: 23.MAY.2025 09:08:11

Freq. Stability 0C 3V ax40 5670MHz Ant1 0 Minutes




Date: 23.MAY.2025 09:08:22


Freq. Stability 10C 3V ax40 5670MHz Ant1 0 Minutes




Freq. Stability 20C 3V ax40 5670MHz Ant1 0 Minutes




Freq. Stability 30C 3V ax40 5670MHz Ant1 0 Minutes



Freq. Stability 40C 3V ax40 5670MHz Ant1 0 Minutes




Freq. Stability 50C 3V ax40 5670MHz Ant1 0 Minutes




Date: 23.MAY.2025 09:09:17

Freq. Stability 20C 2.805V ax40 5190MHz Ant2 0 Minutes




Date: 23.MAY.2025 11:14:39


Freq. Stability 20C 3.3V ax40 5190MHz Ant2 0 Minutes




Freq. Stability 20C 3.795V ax40 5190MHz Ant2 0 Minutes




Freq. Stability -20C 3V ax40 5190MHz Ant2 0 Minutes




Freq. Stability -10C 3V ax40 5190MHz Ant2 0 Minutes




Freq. Stability 0C 3V ax40 5190MHz Ant2 0 Minutes




Freq. Stability 10C 3V ax40 5190MHz Ant2 0 Minutes




Freq. Stability 20C 3V ax40 5190MHz Ant2 0 Minutes



Freq. Stability 30C 3V ax40 5190MHz Ant2 0 Minutes




Freq. Stability 40C 3V ax40 5190MHz Ant2 0 Minutes




Date: 23.MAY.2025 11:16:18

Freq. Stability 50C 3V ax40 5190MHz Ant2 0 Minutes




Date: 23.MAY.2025 11:16:29


Freq. Stability 20C 2.805V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 20C 3.795V ax40 5230MHz Ant2 0 Minutes




Freq. Stability -20C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability -10C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 0C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 10C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 20C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 30C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 40C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 50C 3V ax40 5230MHz Ant2 0 Minutes




Freq. Stability 20C 2.805V ax40 5270MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V ax40 5270MHz Ant2 0 Minutes




Freq. Stability 20C 3.795V ax40 5270MHz Ant2 0 Minutes




Freq. Stability -20C 3V ax40 5270MHz Ant2 0 Minutes




Freq. Stability -10C 3V ax40 5270MHz Ant2 0 Minutes




Freq. Stability 0C 3V ax40 5270MHz Ant2 0 Minutes



Freq. Stability 10C 3V ax40 5270MHz Ant2 0 Minutes




Freq. Stability 20C 3V ax40 5270MHz Ant2 0 Minutes




Date: 23.MAY.2025 11:02:45

Freq. Stability 30C 3V ax40 5270MHz Ant2 0 Minutes




Date: 23.MAY.2025 11:02:56


Freq. Stability 40C 3V ax40 5270MHz Ant2 0 Minutes




Freq. Stability 50C 3V ax40 5270MHz Ant2 0 Minutes




Freq. Stability 20C 2.805V ax40 5310MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V ax40 5310MHz Ant2 0 Minutes




Freq. Stability 20C 3.795V ax40 5310MHz Ant2 0 Minutes




Date: 23.MAY.2025 10:54:55

Freq. Stability -20C 3V ax40 5310MHz Ant2 0 Minutes




Date: 23.MAY.2025 10:55:06


Freq. Stability -10C 3V ax40 5310MHz Ant2 0 Minutes



Freq. Stability 0C 3V ax40 5310MHz Ant2 0 Minutes




Freq. Stability 10C 3V ax40 5310MHz Ant2 0 Minutes




Date: 23.MAY.2025 10:55:39

Freq. Stability 20C 3V ax40 5310MHz Ant2 0 Minutes






Date: 23.MAY.2025 10:55:50

Freq. Stability 30C 3V ax40 5310MHz Ant2 0 Minutes




Freq. Stability 40C 3V ax40 5310MHz Ant2 0 Minutes







Freq. Stability 20C 3.3V ax40 5510MHz Ant2 0 Minutes




Freq. Stability 20C 3.795V ax40 5510MHz Ant2 0 Minutes




Freq. Stability -20C 3V ax40 5510MHz Ant2 0 Minutes




Freq. Stability -10C 3V ax40 5510MHz Ant2 0 Minutes




Freq. Stability 0C 3V ax40 5510MHz Ant2 0 Minutes




Freq. Stability 10C 3V ax40 5510MHz Ant2 0 Minutes




Freq. Stability 20C 3V ax40 5510MHz Ant2 0 Minutes



Freq. Stability 30C 3V ax40 5510MHz Ant2 0 Minutes




Freq. Stability 40C 3V ax40 5510MHz Ant2 0 Minutes




Date: 23.MAY.2025 10:50:21

Freq. Stability 50C 3V ax40 5510MHz Ant2 0 Minutes




Date: 23.MAY.2025 10:50:32


Freq. Stability 20C 2.805V ax40 5590MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V ax40 5590MHz Ant2 0 Minutes




Freq. Stability 20C 3.795V ax40 5590MHz Ant2 0 Minutes



Freq. Stability -20C 3V ax40 5590MHz Ant2 0 Minutes




Freq. Stability -10C 3V ax40 5590MHz Ant2 0 Minutes



Date: 23.MAY.2025 09:24:45

Freq. Stability 0C 3V ax40 5590MHz Ant2 0 Minutes



Date: 23.MAY.2025 09:24:56