

FCC Class II Permissive Change Application Letter

Eurofins Electrical and Electronic Testing NA, Inc.
914 West Patapsco Avenue
Baltimore, MD 21230

Applicant's complete, legal business name: [RM Acquisition LLC](#).

Applicant's mailing address: [18022 Cowan Ste 185, Irvine, California 92614, United States](#)

Equipment Product Code: [-10017A](#)

FCCID Number and Date of Original Grant: [A4C-10017A, DSS/DTS:08/12/2024](#)
[NII:08/13/2024](#)



Person at the Applicant's address to receive Grant (name, title, e-mail):

(Include mailing address if other than above):

[Hans Molin](#)
[Chief Technology Officer](#)
[\(949\) 777-3050](#)
hans.molin@randmcnally.com

Change Contents:

Only the names of HW and SW have been modified. It does not change any RF specification Settings or PCB circuits.

Original	New
1.Changed the applicant's address information.	
1100 West Idaho STreet SUITE 310, Boise, Idaho. 83702.	18022 Cowan Ste 185, Irvine, California 92614, United States
2.Changed the product model number.	
RandTab6	RandOneTab6
3.The software version has been changed	
RandTab6-userdebug 13 TP1A.20220624.014 RandTab6_mp_240429_66 release-keys	RandTab6-userdebug13 TP1A.220624.014 RandTab6_mp_240717_126_diag
4.Changed the hardware version	
RANDTAB6-MAIN-V01A-1	RANDTAB6-MAIN-V01A-2
5.eMMC chip model replacement	
 EMMC: KLMBG2JETD-B041	 EMMC: YMEC7C0TG1A2C3

Sincerely,

[Signature]

A handwritten signature in blue ink, appearing to read "Hm ML", is positioned to the right of the "[Signature]" placeholder.