

5G NR n77 10MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 15MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 10MHz BPSK High Channel RB1-23, ID:27966



5G NR n77 15MHz BPSK Low Channel RB1-37, ID:27966



5G NR n77 10MHz BPSK High Channel RB24-0, ID:27966



5G NR n77 15MHz BPSK Low Channel RB36-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 15MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n77 15MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 15MHz BPSK Middle Channel RB1-37, ID:27966



5G NR n77 15MHz BPSK High Channel RB1-37, ID:27966



5G NR n77 15MHz BPSK Middle Channel RB36-0, ID:27966



5G NR n77 15MHz BPSK High Channel RB36-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 20MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n77 20MHz BPSK Low Channel RB1-50, ID:27966



5G NR n77 20MHz BPSK Middle Channel RB1-50, ID:27966



5G NR n77 20MHz BPSK Low Channel RB50-0, ID:27966



5G NR n77 20MHz BPSK Middle Channel RB50-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 20MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 25MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 20MHz BPSK High Channel RB1-50, ID:27966



5G NR n77 25MHz BPSK Low Channel RB1-64, ID:27966



5G NR n77 20MHz BPSK High Channel RB50-0, ID:27966



5G NR n77 25MHz BPSK Low Channel RB64-0, ID:27966

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 25MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n77 30MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 25MHz BPSK Middle Channel RB1-64, ID:27966



5G NR n77 25MHz BPSK High Channel RB1-64, ID:27966



5G NR n77 25MHz BPSK Middle Channel RB64-0, ID:27966



5G NR n77 25MHz BPSK High Channel RB64-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 30MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 30MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n77 30MHz BPSK Low Channel RB1-77, ID:27966



5G NR n77 30MHz BPSK Middle Channel RB1-77, ID:27966



5G NR n77 30MHz BPSK Low Channel RB75-0, ID:27966



5G NR n77 30MHz BPSK Middle Channel RB75-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 30MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 40MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 30MHz BPSK High Channel RB1-77, ID:27966



5G NR n77 40MHz BPSK Low Channel RB1-105, ID:27966



5G NR n77 30MHz BPSK High Channel RB75-0, ID:27966



5G NR n77 40MHz BPSK Low Channel RB100-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 40MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n77 40MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 40MHz BPSK Middle Channel RB1-105, ID:27966



5G NR n77 40MHz BPSK High Channel RB1-105, ID:27966



5G NR n77 40MHz BPSK Middle Channel RB100-0, ID:27966



5G NR n77 40MHz BPSK High Channel RB100-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 50MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 50MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n77 50MHz BPSK Low Channel RB1-132, ID:27966



5G NR n77 50MHz BPSK Middle Channel RB1-132, ID:27966



5G NR n77 50MHz BPSK Low Channel RB128-0, ID:27966



5G NR n77 50MHz BPSK Middle Channel RB128-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 50MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 60MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 50MHz BPSK High Channel RB1-132, ID:27966



5G NR n77 60MHz BPSK Low Channel RB1-161, ID:27966



5G NR n77 50MHz BPSK High Channel RB128-0, ID:27966



5G NR n77 60MHz BPSK Low Channel RB162-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 60MHz BPSK Middle Channel RB1-0, ID:28498



5G NR n77 60MHz BPSK High Channel RB1-0, ID:27966



5G NR n77 60MHz BPSK Middle Channel RB1-161, ID:27966



5G NR n77 60MHz BPSK High Channel RB1-161, ID:27966



5G NR n77 60MHz BPSK Middle Channel RB162-0, ID:27966



5G NR n77 60MHz BPSK High Channel RB162-0, ID:27966

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 70MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 70MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n77 70MHz BPSK Low Channel RB1-188, ID:27966



5G NR n77 70MHz BPSK Middle Channel RB1-188, ID:27966



5G NR n77 70MHz BPSK Low Channel RB180-0, ID:27966



5G NR n77 70MHz BPSK Middle Channel RB180-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 70MHz BPSK High Channel RB1-0, ID:19210



5G NR n77 80MHz BPSK Low Channel RB1-0, ID:27966



5G NR n77 70MHz BPSK High Channel RB1-188, ID: 19210



5G NR n77 80MHz BPSK Low Channel RB1-216, ID:27966



5G NR n77 70MHz BPSK High Channel RB180-0, ID: 19210



5G NR n77 80MHz BPSK Low Channel RB216-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.