





Plot on 6695 MHz



Plot on 6855 MHz






EUT Mode


802.11ax HE20 FullRU

Plot on 5955 MHz




01:09:17 PM 01/08/2026

Plot on 6195 MHz




01:48:48 PM 01/08/2026

Plot on 6415 MHz



02:20:23 PM 01/08/2026


Plot on 6535 MHz




02:55:37 PM 01/08/2026



Plot on 6695 MHz



Plot on 6855 MHz






EUT Mode


802.11ax HE20 26RU0

Plot on 5955 MHz



01:24:19 PM 01/08/2026

Plot on 6535 MHz




03:07:56 PM 01/08/2026

EUT Mode


802.11ax HE20 26RU4

Plot on 6195 MHz



02:00:10 PM 01/08/2026

Plot on 6695 MHz




03:46:20 PM 01/08/2026



EUT Mode


802.11ax HE20 26RU8

Plot on 6415 MHz



02:32:32 PM 01/08/2026

Plot on 6855 MHz




04:25:21 PM 01/08/2026

EUT Mode


802.11ax HE20 52RU37

Plot on 5955 MHz



01:36:20 PM 01/08/2026

Plot on 6535 MHz




03:18:52 PM 01/08/2026



EUT Mode


802.11ax HE20 52RU38

Plot on 6195 MHz



02:10:09 PM 01/08/2026

Plot on 6695 MHz




03:57:52 PM 01/08/2026

EUT Mode


802.11ax HE20 52RU40

Plot on 6415 MHz



02:43:17 PM 01/08/2026

Plot on 6855 MHz




04:38:18 PM 01/08/2026



EUT Mode


802.11ax HE20 106RU53

Plot on 5955 MHz




01:45:27 PM 01/08/2026

Plot on 6195 MHz




02:17:22 PM 01/08/2026

Plot on 6535 MHz



03:30:24 PM 01/08/2026

Plot on 6695 MHz



04:05:57 PM 01/08/2026





EUT Mode

802.11ax HE20 106RU54

Plot on 6415 MHz

Plot on 6855 MHz






EUT Mode


802.11ax HE40 FullRU

Plot on 5965 MHz




04:54:41 PM 01/08/2026

Plot on 6205 MHz




05:00:55 PM 01/08/2026

Plot on 6405 MHz



05:06:41 PM 01/08/2026


Plot on 6565 MHz




05:13:35 PM 01/08/2026



Plot on 6685 MHz



Plot on 6845 MHz






EUT Mode


802.11ax HE80 FullIRU

Plot on 5985 MHz




05:56:27 PM 01/08/2026

Plot on 6225 MHz




06:03:07 PM 01/08/2026

Plot on 6385 MHz



06:08:47 PM 01/08/2026


Plot on 6625 MHz




06:14:49 PM 01/08/2026



Plot on 6705 MHz



Plot on 6785 MHz






EUT Mode


802.11ax HE160 FullIRU

Plot on 6025 MHz




06:52:49 PM 01/13/2026

Plot on 6185 MHz




12:09:33 AM 01/27/2026

Plot on 6345 MHz



12:24:12 AM 01/27/2026

Plot on 6665 MHz




01:11:46 AM 01/27/2026



EUT Mode


802.11be EHT20 FullIRU

Plot on 5955 MHz




05:18:11 PM 01/07/2026

Plot on 6195 MHz




05:21:39 PM 01/07/2026

Plot on 6415 MHz



05:24:18 PM 01/07/2026


Plot on 6535 MHz




05:29:05 PM 01/07/2026



Plot on 6695 MHz



Plot on 6855 MHz







EUT Mode

802.11be EHT20 26RU0

Plot on 5955 MHz




Plot on 6535 MHz




EUT Mode

802.11be EHT20 26RU4

Plot on 6195 MHz



Plot on 6695 MHz






EUT Mode


802.11be EHT20 26RU8

Plot on 6415 MHz



10:24:37 PM 01/07/2026

Plot on 6855 MHz




02:48:09 AM 01/08/2026

EUT Mode


802.11be EHT20 52RU37

Plot on 5955 MHz



07:53:01 PM 01/07/2026

Plot on 6535 MHz




12:09:38 AM 01/08/2026



EUT Mode


802.11be EHT20 52RU38

Plot on 6195 MHz



09:17:42 PM 01/07/2026

Plot on 6695 MHz




01:42:00 AM 01/08/2026

EUT Mode


802.11be EHT20 52RU40

Plot on 6415 MHz



10:45:12 PM 01/07/2026

Plot on 6855 MHz




03:09:30 AM 01/08/2026



EUT Mode


802.11be EHT20 106RU53

Plot on 5955 MHz




08:08:37 PM 01/07/2026

Plot on 6195 MHz




09:33:19 PM 01/07/2026

Plot on 6535 MHz



12:27:17 AM 01/08/2026

Plot on 6695 MHz




01:56:40 AM 01/08/2026



EUT Mode


802.11be EHT20 106RU54

Plot on 6415 MHz



10:59:51 PM 01/07/2026

Plot on 6855 MHz




03:28:11 AM 01/08/2026

EUT Mode


802.11be EHT20 52T+26T70

Plot on 5955 MHz



08:26:12 PM 01/07/2026

Plot on 6535 MHz



12:46:54 AM 01/08/2026





EUT Mode

802.11be EHT20 52T+26T71

Plot on 6195 MHz

Plot on 6695 MHz





EUT Mode

802.11be EHT20 52T+26T72

Plot on 6415 MHz

Plot on 6855 MHz






EUT Mode

802.11be EHT20 106T+26T82

Plot on 5955 MHz

Plot on 6535 MHz






EUT Mode


802.11be EHT20 106T+26T83

Plot on 6195 MHz




10:02:35 PM 01/07/2026

Plot on 6415 MHz




11:27:10 PM 01/07/2026

Plot on 6695 MHz



02:25:00 AM 01/08/2026

Plot on 6855 MHz




09:33:18 AM 01/08/2026



EUT Mode


802.11be EHT40 FullRU

Plot on 5965 MHz




05:40:24 PM 01/07/2026

Plot on 6205 MHz




05:47:22 PM 01/07/2026

Plot on 6405 MHz



05:53:28 PM 01/07/2026


Plot on 6565 MHz




06:00:47 PM 01/07/2026



Plot on 6685 MHz



Plot on 6845 MHz






EUT Mode


802.11be EHT80 FullRU

Plot on 5985 MHz




06:16:51 PM 01/07/2026

Plot on 6225 MHz




06:22:53 PM 01/07/2026

Plot on 6385 MHz



06:28:06 PM 01/07/2026


Plot on 6625 MHz




06:33:20 PM 01/07/2026



Plot on 6705 MHz



Plot on 6785 MHz






EUT Mode


802.11be EHT80 Puncture20 1

Plot on 6385 MHz



10:27:25 AM 01/08/2026

Plot on 6785 MHz




11:41:02 AM 01/08/2026

EUT Mode


802.11be EHT80 Puncture20 2

Plot on 6225 MHz



09:54:47 AM 01/08/2026

Plot on 6705 MHz




11:05:31 AM 01/08/2026



EUT Mode


802.11be EHT80 Puncture20 4

Plot on 6225 MHz



10:10:30 AM 01/08/2026

Plot on 6705 MHz




11:22:16 AM 01/08/2026

EUT Mode


802.11be EHT80 Puncture20 8

Plot on 5985 MHz



09:37:04 AM 01/08/2026

Plot on 6625 MHz




10:39:43 AM 01/08/2026




EUT Mode

802.11be EHT160 FullIRU


Plot on 6025 MHz




Plot on 6185 MHz



Plot on 6345 MHz



Plot on 6665 MHz






EUT Mode

802.11be EHT160 Puncture20 1


Plot on 6345 MHz



EUT Mode

802.11be EHT160 Puncture20 16

Plot on 6185 MHz






EUT Mode

802.11be EHT160 Puncture20 128

Plot on 6025 MHz


Plot on 6665 MHz



EUT Mode

802.11be EHT160 Puncture40 3

Plot on 6345 MHz






EUT Mode

802.11be EHT160 Puncture40 48

Plot on 6185 MHz




04:30:14 PM 01/26/2026

EUT Mode


802.11be EHT160 Puncture40 192

Plot on 6025 MHz



06:43:13 PM 01/13/2026

Plot on 6665 MHz



03:57:22 PM 02/12/2026