




EUT Mode


802.11be EHT20 106T+26T83

Plot on 6195 MHz




11:49:54 PM 02/10/2026

Plot on 6415 MHz




12:01:30 AM 02/11/2026

Plot on 6475 MHz



12:26:00 AM 02/11/2026


Plot on 6515 MHz




12:38:14 AM 02/11/2026




Plot on 6695 MHz




Plot on 6855 MHz



Plot on 6875 MHz




Plot on 6995 MHz





Plot on 7095 MHz







EUT Mode

802.11be EHT40 FullRU


Plot on 5965 MHz




Plot on 6205 MHz



Plot on 6405 MHz




Plot on 6445 MHz







Plot on 6485 MHz




Plot on 6565 MHz



Plot on 6685 MHz




Plot on 6845 MHz







Plot on 6885 MHz




Plot on 6925 MHz




Plot on 7005 MHz



Plot on 7085 MHz



Plot on 6525 MHz






EUT Mode


802.11be EHT80 FullIRU

Plot on 5985 MHz




02:52:49 AM 02/11/2026

Plot on 6225 MHz




02:58:01 AM 02/11/2026

Plot on 6385 MHz



03:05:00 AM 02/11/2026


Plot on 6465 MHz




03:10:20 AM 02/11/2026




Plot on 6625 MHz




Plot on 6705 MHz



Plot on 6785 MHz




Plot on 6865 MHz







Plot on 6945 MHz



Plot on 7025 MHz



Plot on 6545 MHz






EUT Mode


802.11be EHT80 Puncture20 1

Plot on 6385 MHz




03:06:51 AM 02/11/2026

Plot on 6785 MHz




03:35:32 AM 02/11/2026

Plot on 6865 MHz



03:40:50 AM 02/11/2026

Plot on 7025 MHz



03:51:44 AM 02/11/2026





EUT Mode

802.11be EHT80 Puncture20 2

Plot on 6225 MHz

Plot on 6705 MHz





EUT Mode

802.11be EHT80 Puncture20 4

Plot on 6225 MHz

Plot on 6705 MHz






EUT Mode


802.11be EHT80 Puncture20 8

Plot on 5985 MHz




02:54:39 AM 02/11/2026

Plot on 6465 MHz




03:12:16 AM 02/11/2026

Plot on 6625 MHz



03:22:45 AM 02/11/2026


Plot on 6945 MHz



03:46:15 AM 02/11/2026



Plot on 6545 MHz







EUT Mode

802.11be EHT160 FullIRU


Plot on 6025 MHz




Plot on 6185 MHz



Plot on 6345 MHz




Plot on 6665 MHz







Plot on 6825 MHz



Plot on 6985 MHz



Plot on 6505 MHz






EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6345 MHz




03:56:39 PM 02/11/2026

Plot on 6985 MHz



04:44:06 PM 02/11/2026

Plot on 6505 MHz




04:05:02 PM 02/11/2026



EUT Mode

802.11be EHT160 Puncture20 16

Plot on 6185 MHz






EUT Mode


802.11be EHT160 Puncture20 128

Plot on 6025 MHz

Plot on 6665 MHz




03:37:15 PM 02/11/2026



04:12:08 PM 02/11/2026

Plot on 6825 MHz




04:28:52 PM 02/11/2026




EUT Mode

802.11be EHT160 Puncture40 3


Plot on 6345 MHz



Plot on 6985 MHz



Plot on 6505 MHz









EUT Mode

802.11be EHT160 Puncture40 48

Plot on 6185 MHz



**EUT Mode****802.11be EHT160 Puncture40 192****Plot on 6025 MHz****Plot on 6665 MHz****Plot on 6825 MHz**




MIMO <Ant. 3+4 (4)>

EUT Mode


802.11a

Plot on 5955 MHz




10:26:57 PM 02/10/2026

Plot on 6195 MHz




10:30:16 PM 02/10/2026

Plot on 6415 MHz



10:33:54 PM 02/10/2026


Plot on 6435 MHz



10:37:22 PM 02/10/2026




Plot on 6475 MHz




10:40:47 PM 02/10/2026

Plot on 6515 MHz




10:44:06 PM 02/10/2026

Plot on 6535 MHz



10:47:29 PM 02/10/2026


Plot on 6695 MHz



10:50:44 PM 02/10/2026




Plot on 6855 MHz




10:54:11 PM 02/10/2026

Plot on 6875 MHz




10:57:42 PM 02/10/2026

Plot on 6895 MHz




11:08:29 PM 02/10/2026

Plot on 6995 MHz



11:11:41 PM 02/10/2026

Plot on 7095 MHz




11:15:04 PM 02/10/2026



EUT Mode


802.11ax HE20 FullIRU

Plot on 5955 MHz




11:55:06 AM 02/11/2026

Plot on 6195 MHz




12:02:44 PM 02/11/2026

Plot on 6415 MHz



12:10:19 PM 02/11/2026


Plot on 6435 MHz




12:17:53 PM 02/11/2026




Plot on 6475 MHz




Plot on 6515 MHz



Plot on 6535 MHz




Plot on 6695 MHz






Plot on 6855 MHz




12:56:03 PM 02/11/2026

Plot on 6875 MHz




01:03:42 PM 02/11/2026

Plot on 6895 MHz




01:11:22 PM 02/11/2026

Plot on 6995 MHz



01:18:58 PM 02/11/2026

Plot on 7095 MHz




01:26:35 PM 02/11/2026



EUT Mode


802.11ax HE20 26RU0

Plot on 5955 MHz




11:56:53 AM 02/11/2026

Plot on 6435 MHz




12:19:38 PM 02/11/2026

Plot on 6535 MHz



12:42:30 PM 02/11/2026

Plot on 6895 MHz




01:13:06 PM 02/11/2026



EUT Mode


802.11ax HE20 26RU4

Plot on 6195 MHz




12:04:27 PM 02/11/2026

Plot on 6475 MHz




12:27:13 PM 02/11/2026

Plot on 6695 MHz



12:50:08 PM 02/11/2026

Plot on 6995 MHz




01:20:42 PM 02/11/2026



EUT Mode


802.11ax HE20 26RU8

Plot on 6415 MHz




12:12:01 PM 02/11/2026

Plot on 6515 MHz




12:34:51 PM 02/11/2026

Plot on 6855 MHz



12:57:46 PM 02/11/2026


Plot on 6875 MHz



01:05:25 PM 02/11/2026



Plot on 7095 MHz






EUT Mode


802.11ax HE20 52RU37

Plot on 5955 MHz




11:58:37 AM 02/11/2026

Plot on 6435 MHz




12:21:21 PM 02/11/2026

Plot on 6535 MHz



12:44:14 PM 02/11/2026

Plot on 6895 MHz




01:14:50 PM 02/11/2026



EUT Mode


802.11ax HE20 52RU38

Plot on 6195 MHz




12:06:10 PM 02/11/2026

Plot on 6475 MHz




12:28:59 PM 02/11/2026

Plot on 6695 MHz



12:51:52 PM 02/11/2026

Plot on 6995 MHz




01:22:26 PM 02/11/2026



EUT Mode


802.11ax HE20 52RU40

Plot on 6415 MHz




12:13:45 PM 02/11/2026

Plot on 6515 MHz




12:36:34 PM 02/11/2026

Plot on 6855 MHz



12:59:29 PM 02/11/2026


Plot on 6875 MHz



01:07:11 PM 02/11/2026



Plot on 7095 MHz






EUT Mode


802.11ax HE20 106RU53

Plot on 5955 MHz




12:00:20 PM 02/11/2026

Plot on 6195 MHz




12:07:55 PM 02/11/2026

Plot on 6435 MHz



12:23:05 PM 02/11/2026


Plot on 6475 MHz




12:30:42 PM 02/11/2026




Plot on 6535 MHz




Plot on 6695 MHz



Plot on 6895 MHz



Plot on 6995 MHz







EUT Mode

802.11ax HE20 106RU54


Plot on 6415 MHz




Plot on 6515 MHz



Plot on 6855 MHz




Plot on 6875 MHz





Plot on 7095 MHz






EUT Mode


802.11ax HE40 FullRU

Plot on 5965 MHz




01:34:11 PM 02/11/2026

Plot on 6205 MHz




01:36:35 PM 02/11/2026

Plot on 6405 MHz



01:39:00 PM 02/11/2026


Plot on 6445 MHz




01:41:24 PM 02/11/2026




Plot on 6485 MHz




Plot on 6565 MHz



Plot on 6685 MHz




Plot on 6845 MHz






Plot on 6885 MHz




01:55:57 PM 02/11/2026

Plot on 6925 MHz




01:58:23 PM 02/11/2026

Plot on 7005 MHz




02:00:49 PM 02/11/2026

Plot on 7085 MHz



02:03:14 PM 02/11/2026

Plot on 6525 MHz




02:46:15 PM 02/11/2026



EUT Mode


802.11ax HE80 FullIRU

Plot on 5985 MHz




02:05:41 PM 02/11/2026

Plot on 6225 MHz




02:08:07 PM 02/11/2026

Plot on 6385 MHz



02:10:32 PM 02/11/2026


Plot on 6465 MHz




02:12:57 PM 02/11/2026




Plot on 6625 MHz




Plot on 6705 MHz



Plot on 6785 MHz




Plot on 6865 MHz







Plot on 6945 MHz



Plot on 7025 MHz



Plot on 6545 MHz







EUT Mode

802.11ax HE160 FullIRU


Plot on 6025 MHz




Plot on 6185 MHz



Plot on 6345 MHz




Plot on 6665 MHz






Plot on 6825 MHz




05:02:37 PM 02/11/2026

Plot on 6985 MHz



05:06:28 PM 02/11/2026

Plot on 6505 MHz



04:52:01 PM 02/11/2026