






Plot on 6475 MHz




Plot on 6515 MHz



Plot on 6535 MHz




Plot on 6695 MHz






Plot on 6855 MHz




07:15:39 PM 02/10/2026

Plot on 6875 MHz




07:20:10 PM 02/10/2026

Plot on 6895 MHz




07:24:42 PM 02/10/2026

Plot on 6995 MHz



07:29:13 PM 02/10/2026

Plot on 7095 MHz




07:33:45 PM 02/10/2026



EUT Mode


802.11be EHT20 26RU0

Plot on 5955 MHz




06:40:11 PM 02/10/2026

Plot on 6435 MHz




06:53:43 PM 02/10/2026

Plot on 6535 MHz



07:07:15 PM 02/10/2026

Plot on 6895 MHz




07:25:20 PM 02/10/2026



EUT Mode


802.11be EHT20 26RU4

Plot on 6195 MHz




06:44:40 PM 02/10/2026

Plot on 6475 MHz




06:58:13 PM 02/10/2026

Plot on 6695 MHz



07:11:47 PM 02/10/2026

Plot on 6995 MHz




07:29:51 PM 02/10/2026



EUT Mode


802.11be EHT20 26RU8

Plot on 6415 MHz




06:49:11 PM 02/10/2026

Plot on 6515 MHz




07:02:44 PM 02/10/2026

Plot on 6855 MHz



07:16:18 PM 02/10/2026


Plot on 6875 MHz



07:20:49 PM 02/10/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 52RU37

Plot on 5955 MHz




06:40:49 PM 02/10/2026

Plot on 6435 MHz




06:54:21 PM 02/10/2026

Plot on 6535 MHz



07:07:54 PM 02/10/2026

Plot on 6895 MHz




07:25:58 PM 02/10/2026



EUT Mode


802.11be EHT20 52RU38

Plot on 6195 MHz




06:45:19 PM 02/10/2026

Plot on 6475 MHz




06:58:51 PM 02/10/2026

Plot on 6695 MHz



07:12:25 PM 02/10/2026

Plot on 6995 MHz




07:30:30 PM 02/10/2026



EUT Mode


802.11be EHT20 52RU40

Plot on 6415 MHz




06:49:50 PM 02/10/2026

Plot on 6515 MHz




07:03:22 PM 02/10/2026

Plot on 6855 MHz



07:16:57 PM 02/10/2026


Plot on 6875 MHz



07:21:27 PM 02/10/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 106RU53

Plot on 5955 MHz




06:41:27 PM 02/10/2026

Plot on 6195 MHz




06:45:57 PM 02/10/2026

Plot on 6435 MHz



06:54:59 PM 02/10/2026


Plot on 6475 MHz




06:59:30 PM 02/10/2026




Plot on 6535 MHz




Plot on 6695 MHz



Plot on 6895 MHz



Plot on 6995 MHz






EUT Mode


802.11be EHT20 106RU54

Plot on 6415 MHz




06:50:29 PM 02/10/2026

Plot on 6515 MHz




07:04:00 PM 02/10/2026

Plot on 6855 MHz



07:17:35 PM 02/10/2026


Plot on 6875 MHz



07:22:06 PM 02/10/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 52T+26T70

Plot on 5955 MHz




06:42:06 PM 02/10/2026

Plot on 6435 MHz




06:55:37 PM 02/10/2026

Plot on 6535 MHz



07:09:11 PM 02/10/2026

Plot on 6895 MHz




07:27:15 PM 02/10/2026



EUT Mode


802.11be EHT20 52T+26T71

Plot on 6195 MHz




06:46:35 PM 02/10/2026

Plot on 6475 MHz




07:00:08 PM 02/10/2026

Plot on 6695 MHz



07:13:42 PM 02/10/2026

Plot on 6995 MHz




07:31:47 PM 02/10/2026



EUT Mode


802.11be EHT20 52T+26T72

Plot on 6415 MHz




06:51:07 PM 02/10/2026

Plot on 6515 MHz




07:04:39 PM 02/10/2026

Plot on 6855 MHz



07:18:13 PM 02/10/2026


Plot on 6875 MHz



07:22:44 PM 02/10/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 106T+26T82

Plot on 5955 MHz




06:42:44 PM 02/10/2026

Plot on 6435 MHz




06:56:15 PM 02/10/2026

Plot on 6535 MHz



07:09:50 PM 02/10/2026

Plot on 6895 MHz




07:27:54 PM 02/10/2026



EUT Mode


802.11be EHT20 106T+26T83

Plot on 6195 MHz




06:47:13 PM 02/10/2026

Plot on 6415 MHz




06:51:45 PM 02/10/2026

Plot on 6475 MHz



07:00:47 PM 02/10/2026


Plot on 6515 MHz



07:05:18 PM 02/10/2026




Plot on 6695 MHz




07:14:20 PM 02/10/2026

Plot on 6855 MHz




07:18:51 PM 02/10/2026

Plot on 6875 MHz




07:23:23 PM 02/10/2026

Plot on 6995 MHz



07:32:26 PM 02/10/2026

Plot on 7095 MHz




07:36:57 PM 02/10/2026



EUT Mode


802.11be EHT40 FullIRU

Plot on 5965 MHz




07:39:16 PM 02/10/2026

Plot on 6205 MHz




07:39:34 PM 02/10/2026

Plot on 6405 MHz



07:40:54 PM 02/10/2026


Plot on 6445 MHz




07:42:13 PM 02/10/2026




Plot on 6485 MHz




Plot on 6565 MHz



Plot on 6685 MHz




Plot on 6845 MHz







Plot on 6885 MHz




Plot on 6925 MHz




Plot on 7005 MHz



Plot on 7085 MHz



Plot on 6525 MHz







EUT Mode

802.11be EHT80 FullIRU


Plot on 5985 MHz




Plot on 6225 MHz



Plot on 6385 MHz




Plot on 6465 MHz







Plot on 6625 MHz




Plot on 6705 MHz



Plot on 6785 MHz




Plot on 6865 MHz







Plot on 6945 MHz



Plot on 7025 MHz



Plot on 6545 MHz







EUT Mode

802.11be EHT80 Puncture20 1


Plot on 6385 MHz




Plot on 6785 MHz



Plot on 6865 MHz



Plot on 7025 MHz







EUT Mode

802.11be EHT80 Puncture20 2

Plot on 6225 MHz

Plot on 6705 MHz









EUT Mode

802.11be EHT80 Puncture20 4

Plot on 6225 MHz


Plot on 6705 MHz



**EUT Mode****802.11be EHT80 Puncture20 8****Plot on 5985 MHz****Plot on 6465 MHz****Plot on 6625 MHz****Plot on 6945 MHz**



Plot on 6545 MHz






EUT Mode


802.11be EHT160 FullIRU

Plot on 6025 MHz




08:18:29 PM 02/10/2026

Plot on 6185 MHz




08:21:05 PM 02/10/2026

Plot on 6345 MHz



08:23:43 PM 02/10/2026


Plot on 6665 MHz




08:28:56 PM 02/10/2026




Plot on 6825 MHz



Plot on 6985 MHz



Plot on 6505 MHz






EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6345 MHz




08:24:22 PM 02/10/2026

Plot on 6985 MHz



08:35:05 PM 02/10/2026

Plot on 6505 MHz




08:26:59 PM 02/10/2026



EUT Mode

802.11be EHT160 Puncture20 16

Plot on 6185 MHz






EUT Mode


802.11be EHT160 Puncture20 128

Plot on 6025 MHz

Plot on 6665 MHz




08:19:08 PM 02/10/2026



08:29:35 PM 02/10/2026

Plot on 6825 MHz



08:32:19 PM 02/10/2026




EUT Mode


802.11be EHT160 Puncture40 3

Plot on 6345 MHz

Plot on 6985 MHz




08:25:01 PM 02/10/2026



08:35:45 PM 02/10/2026

Plot on 6505 MHz




08:27:38 PM 02/10/2026



EUT Mode

802.11be EHT160 Puncture40 48

Plot on 6185 MHz






EUT Mode


802.11be EHT160 Puncture40 192

Plot on 6025 MHz




08:15:47 PM 02/10/2026

Plot on 6665 MHz



08:30:15 PM 02/10/2026

Plot on 6825 MHz



08:32:59 PM 02/10/2026