LTE BAND 14 EMISSION MASK



LTE B14 5MHz QPS Low Channel RB1-0, ID:27979



LTE B14 5MHz QPSK High Channel RB1-24, ID:27979



LTE B14 5MHz QPSK Low Channel RB25-0, ID:27979



LTE B14 5MHz QPSK High Channel RB25-0, ID:27979



LTE B14 10MHz QPSK Middle Channel RB1-0, ID:27979



LTE B14 10MHz QPSK Middle Channel RB1-49, ID:27979

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B14 10MHz QPSK Middle Channel RB50-0, ID:27979

Intentionally Blank

5G NR n14 EMISSION MASK



5G NR n14 5MHz BPSK Low Channel RB1-0, ID:50822



5G NR n14 5MHz BPSK High Channel RB1-24, ID:50822



5G NR n14 5MHz BPSK Low Channel RB25-0, ID:50822



5G NR n14 5MHz BPSK High Channel RB25-0, ID:50822

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n14 10MHz BPSK Middle Channel RB1-0, ID:50822



5G NR n14 10MHz BPSK Middle Channel RB1-51, ID:27966



5G NR n14 10MHz BPSK Middle Channel RB50-0, ID:27966

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

FORM NO: CCSUP4031B
FAX: (510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.6. LTE BAND 17

LIMITS

FCC: §27.53
(g) For operations in the 600 MHz band and the 698-746 MHz band, the power of any emission outside a licensee's frequency band(s) of operation shall be attenuated below the transmitter power (P) within the licensed band(s) of operation, measured in watts, by at least 43 + 10 log (P) dB. Compliance with this provision is based on the use of measurement instrumentation employing a resolution bandwidth of 100 kilohertz or greater. However, in the 100 kilohertz bands immediately outside and adjacent to a licensee's frequency block, a resolution bandwidth of at least 30 kHz may be employed.

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B17 5MHz QPSK Low Channel RB1-0, ID:27979



LTE B17 5MHz QPSK High Channel RB1-0, ID:27979



LTE B17 5MHz QPSK Low Channel RB1-24, ID:27979



LTE B17 5MHz QPSK High Channel RB1-24, ID:27979



LTE B17 5MHz QPSK Low Channel RB25-0, ID:27979



LTE B17 5MHz QPSK High Channel RB25-0, ID:27979

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B17 10MHz QPSK Low Channel RB1-0, ID:27979



LTE B17 5MHz QPSK High Channel RB25-0, ID:27979



LTE B17 10MHz QPSK Low Channel RB1-49, ID:27979



LTE B17 10MHz QPSK High Channel RB1-49, ID:27979



LTE B17 10MHz QPSK Low Channel RB50-0, ID:27979



LTE B17 10MHz QPSK High Channel RB50-0, ID:27979

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.7. LTE BAND 25 AND 5G NR n25

LIMITS

FCC: §24.238 (a)
The power of any emission outside of the authorized operating frequency ranges must be attenuated below the transmitting power (P) by a factor of at least 43 + 10 log (P) dB.

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LTE BAND 25 BANDEDGE



LTE B25 1.4MHz QPSK Low Channel RB1-0, ID:27979



LTE B25 1.4MHz QPSK High Channel RB1-5, ID:27979



LTE B25 1.4MHz QPSK Low Channel RB6-0, ID:27979



LTE B25 1.4MHz QPSK High Channel RB6-0, ID:27979



LTE B25 3MHz QPSK Low Channel RB1-0, ID:27979



LTE B25 3MHz QPSK High Channel RB1-14, ID:27979

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 3MHz QPSK Low Channel RB15-0, ID:27979



LTE B25 3MHz QPSK High Channel RB15-0, ID:27979



LTE B25 5MHz QPSK Low Channel RB1-0, ID:27979



LTE B25 5MHz QPSK High Channel RB1-24, ID:27979



LTE B25 5MHz QPSK Low Channel RB25-0, ID:27979



LTE B25 5MHz QPSK High Channel RB25-0, ID:27979

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 10MHz QPSK Low Channel RB1-0, ID:27979



LTE B25 10MHz QPSK High Channel RB1-49, ID:27979



LTE B25 10MHz QPSK Low Channel RB50-0, ID:27979



LTE B25 10MHz QPSK High Channel RB50-0, ID:27979



LTE B25 15MHz QPSK Low Channel RB1-0, ID:27979



LTE B25 15MHz QPSK High Channel RB1-74, ID:27979

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 15MHz QPSK Low Channel RB75-0, ID:27979



LTE B25 15MHz QPSK High Channel RB75-0, ID:27979



LTE B25 20MHz QPSK Low Channel RB1-0, ID:27979



LTE B25 20MHz QPSK High Channel RB1-99, ID:27979



LTE B25 20MHz QPSK Low Channel RB100-0, ID:27979



LTE B25 20MHz QPSK High Channel RB100-0, ID:27979

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n25 BANDEDGE



5G NR n25 5MHz BPSK Low Channel RB1-0, ID:50822



5G NR n25 5MHz BPSK High Channel RB1-24, ID:50822



5G NR n25 5MHz BPSK Low Channel RB25-0, ID:50822



5G NR n25 5MHz BPSK High Channel RB25-0, ID:50822



5G NR n25 10MHz BPSK Low Channel RB1-0, ID:50822



5G NR n25 10MHz BPSK High Channel RB1-51, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n25 10MHz BPSK Low Channel RB50-0, ID: 27966



5G NR n25 10MHz BPSK High Channel RB50-0, ID: 27966



5G NR n25 15MHz BPSK Low Channel RB1-0, ID:50822



5G NR n25 15MHz BPSK High Channel RB1-78, ID:27966



5G NR n25 15MHz BPSK Low Channel RB75-0, ID:27966



5G NR n25 15MHz BPSK High Channel RB75-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n25 20MHz BPSK Low Channel RB1-0, ID:50822



5G NR n25 20MHz BPSK High Channel RB1-105, ID:50822



5G NR n25 20MHz BPSK Low Channel RB100-0, ID:50822



5G NR n25 20MHz BPSK High Channel RB100-0, ID:50822



5G NR n25 25MHz BPSK Low Channel RB1-0, ID:50822



5G NR n25 25MHz BPSK High Channel RB1-132, ID:50822

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n25 25MHz BPSK Low Channel RB128-0, ID:50822



5G NR n25 25MHz BPSK High Channel RB128-0, ID:50822



5G NR n25 30MHz BPSK Low Channel RB1-0, ID:50822



5G NR n25 30MHz BPSK High Channel RB1-159, ID:50822



5G NR n25 30MHz BPSK Low Channel RB160-0, ID:50822



5G NR n25 30MHz BPSK High Channel RB160-0, ID:50822

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.