5G NR n30 EMISSION MASK



5G NR n30 5MHz BPSK Low Channel RB1-0 (Low side), ID:27966



5G NR n30 5MHz BPSK Low Channel RB1-0 (High side), ID:27966



5G NR n30 5MHz BPSK Low Channel RB1-24 (Low side), ID:27966



5G NR n30 5MHz BPSK Low Channel RB1-24 (High side), ID:27966



5G NR n30 5MHz BPSK Low Channel RB25-0 (Low side) , ID:27966



5G NR n30 5MHz BPSK Low Channel RB25-0 (High side), ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n30 5MHz BPSK High Channel RB1-0 (Low side), ID:27966



5G NR n30 5MHz BPSK High Channel RB1-0 (High side), ID:27966



5G NR n30 5MHz BPSK High Channel RB1-24 (Low side), ID:27966



5G NR n30 5MHz BPSK High Channel RB1-24 (High side), ID:27966



5G NR n30 5MHz BPSK High Channel RB25-0 (Low side), ID:27966



5G NR n30 5MHz BPSK High Channel RB25-0 (High side), ID:27966

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n30 10MHz BPSK Middle Channel RB1-0, ID:50822



5G NR n30 10MHz BPSK Middle Channel RB1-51, ID:50822



5G NR n30 10MHz BPSK Middle Channel RB50-0, ID:50822

Intentionally Blank

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.2.11. LTE BAND 41 AND 5G NR n41HPUE

LIMITS

FCC: §27.53
(m)(4) For mobile digital stations, the attenuation factor shall be not less than 40 + 10 log (P) dB on all frequencies between the channel edge and 5 megahertz from the channel edge, 43 + 10 log (P) dB on all frequencies between 5 megahertz and X megahertz from the channel edge, and 55 + 10 log (P) dB on all frequencies more than X megahertz from the channel edge, where X is the greater of 6 megahertz or the actual emission bandwidth as defined in paragraph (m)(6) of this section. In addition, the attenuation factor shall not be less that 43 + 10 log (P) dB on all frequencies between 2490.5 MHz and 2496 MHz and 55 + 10 log (P) dB at or below 2490.5 MHz. Mobile Satellite Service licensees operating on frequencies below 2495 MHz may also submit a documented interference complaint against BRS licensees operating on channel BRS Channel 1 on the same terms and conditions as adjacent channel BRS or EBS licensees.

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LTE BAND 41 ADJACENT CHANNEL POWER



LTE B41 5MHz QPSK Low Channel RB1-0, ID:39005



LTE B41 5MHz QPSK Middle Channel RB1-0, ID:39005



LTE B41 5MHz QPSK Low Channel RB1-24, ID:39005



LTE B41 5MHz QPSK Middle Channel RB1-24, ID:39005



LTE B41 5MHz QPSK Low Channel RB25-0, ID:39005



LTE B41 5MHz QPSK Middle Channel RB25-0, ID:39005

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 5MHz QPSK High Channel RB1-0, ID:39005



LTE B41 10MHz QPSK Low Channel RB1-0, ID:39005



LTE B41 5MHz QPSK High Channel RB1-24, ID:39005



LTE B41 10MHz QPSK Low Channel RB1-49, ID:39005



LTE B41 5MHz QPSK High Channel RB25-0, ID:39005



LTE B41 10MHz QPSK Low Channel RB50-0, ID:39005

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 10MHz QPSK Middle Channel RB1-0, ID:39005



LTE B41 10MHz QPSK High Channel RB1-0, ID:39005



LTE B41 10MHz QPSK Middle Channel RB1-49, ID:39005



LTE B41 10MHz QPSK High Channel RB1-49, ID:39005



LTE B41 10MHz QPSK Middle Channel RB50-0, ID:39005



LTE B41 10MHz QPSK High Channel RB50-0, ID:39005

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 15MHz QPSK Low Channel RB1-0, ID:27966



LTE B41 15MHz QPSK Middle Channel RB1-0, ID:19210



LTE B41 15MHz QPSK Low Channel RB1-74, ID:19210



LTE B41 15MHz QPSK Middle Channel RB1-74, ID:19210



LTE B41 15MHz QPSK Low Channel RB75-0, ID:19210



LTE B41 15MHz QPSK Middle Channel RB75-0, ID:19210

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 15MHz QPSK High Channel RB1-0, ID:19210



LTE B41 20MHz QPSK Low Channel RB1-0, ID:19210



LTE B41 15MHz QPSK High Channel RB1-74, ID:19210



LTE B41 20MHz QPSK Low Channel RB1-99, ID:19210



LTE B41 15MHz QPSK High Channel RB75-0, ID:19210



LTE B41 20MHz QPSK Low Channel RB100-0, ID:19210

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888

FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 20MHz QPSK Middle Channel RB1-0, ID:19210



LTE B41 20MHz QPSK High Channel RB1-0, ID:19210



LTE B41 20MHz QPSK Middle Channel RB1-99, ID:19210



LTE B41 20MHz QPSK High Channel RB1-99, ID:19210



LTE B41 20MHz QPSK Middle Channel RB100-0, ID:19210



LTE B41 20MHz QPSK High Channel RB100-0, ID:19210

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n41 ADJACENT CHANNEL POWER (FCC)



5G NR n41 10MHz BPSK Low Channel RB1-0, ID:19210



5G NR n41 10MHz BPSK Middle Channel RB1-0, ID:19210



5G NR n41 10MHz BPSK Low Channel RB1-23, ID:19210



5G NR n41 10MHz BPSK Middle Channel RB1-23, ID:19210



5G NR n41 10MHz BPSK Low Channel RB24-0, ID:19210



5G NR n41 10MHz BPSK Middle Channel RB24-0, ID:19210

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 10MHz BPSK High Channel RB1-0, ID:19210



5G NR n41 15MHz BPSK Low Channel RB1-0, ID:19210



5G NR n41 10MHz BPSK High Channel RB1-23, ID:19210



5G NR n41 15MHz BPSK Low Channel RB1-37, ID:19210



5G NR n41 10MHz BPSK High Channel RB24-0, ID:19210



5G NR n41 15MHz BPSK Low Channel RB36-0, ID:19210

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 15MHz BPSK Middle Channel RB1-0, ID:19210



5G NR n41 15MHz BPSK High Channel RB1-0, ID:19210



5G NR n41 15MHz BPSK Middle Channel RB1-37, ID:19210



5G NR n41 15MHz BPSK High Channel RB1-37, ID:19210



5G NR n41 15MHz BPSK Middle Channel RB36-0, ID:19210



5G NR n41 15MHz BPSK High Channel RB36-0, ID:19210

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 20MHz BPSK Low Channel RB1-0, ID:27966



5G NR n41 20MHz BPSK Middle Channel RB1-0, ID:27966



5G NR n41 20MHz BPSK Low Channel RB1-50, ID:27966



5G NR n41 20MHz BPSK Middle Channel RB1-50, ID:27966



5G NR n41 20MHz BPSK Low Channel RB50-0, ID:27966



5G NR n41 20MHz BPSK Middle Channel RB50-0, ID:27966

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.