




Annex H


Occupied Bandwidth



Uplink_CDMA Input_1850 - 1915 MHz




Uplink_CDMA Input_698 - 716 MHz






Uplink_CDMA Input_824 - 849 MHz




Uplink_CDMA Output_1850 - 1915 MHz






Uplink_CDMA Output_698 - 716 MHz




Uplink_CDMA Output_824 - 849 MHz






Uplink_GSM Input_1850 - 1915 MHz




Uplink_GSM Input_698 - 716 MHz






Uplink_GSM Input_824 - 849 MHz




Uplink_GSM Output_1850 - 1915 MHz






Uplink_GSM Output_698 - 716 MHz




Uplink_GSM Output_824 - 849 MHz






Uplink_WCDMA Input_1850 - 1915 MHz




Uplink_WCDMA Input_698 - 716 MHz






Uplink_WCDMA Input_824 - 849 MHz




Uplink_WCDMA Output_1850 - 1915 MHz






Uplink_WCDMA Output_698 - 716 MHz




Uplink_WCDMA Output_824 - 849 MHz






Downlink_CDMA Input_1930 - 1995 MHz




Downlink_CDMA Input_738 - 746 MHz






Downlink_CDMA Input_869 - 894 MHz




Downlink_CDMA Output_1930 - 1995 MHz






Downlink_CDMA Output_738 - 746 MHz




Downlink_CDMA Output_869 - 894 MHz






Downlink_GSM Input_1930 - 1995 MHz




Downlink_GSM Input_728 - 746 MHz






Downlink_GSM Input_869 - 894 MHz




Downlink_GSM Output_1930 - 1995 MHz






Downlink_GSM Output_728 - 746 MHz




Downlink_GSM Output_869 - 894 MHz






Downlink_WCDMA Input_1930 - 1995 MHz




Downlink_WCDMA Input_738 - 746 MHz






Downlink_WCDMA Input_869 - 894 MHz




Downlink_WCDMA Output_1930 - 1995 MHz





Downlink_WCDMA Output_738 - 746 MHz



Downlink_WCDMA Output_869 - 894 MHz

