




Annex I


Anti-Oscillation



Oscillation Detection_Downlink_1930-1995 MHz




Oscillation Detection_Downlink_728-746 MHz






Oscillation Detection_Downlink_869-894 MHz




Oscillation Detection_Uplink_1850 - 1915 MHz






Oscillation Detection_Uplink_698 - 716 MHz




Oscillation Detection_Uplink_824 - 849 MHz






Restart Time_Downlink_1930-1995 MHz




Restart Time_Downlink_728-746 MHz






Restart Time_Downlink_869-894 MHz




Restart Time_Uplink_1850 - 1915 MHz






Restart Time_Uplink_698 - 716 MHz




Restart Time_Uplink_824 - 849 MHz






of restarts_Downlink_1930-1995 MHz




of restarts_Downlink_728-746 MHz






of restarts_Downlink_869-894 MHz




of Restarts_Uplink_1850 - 1915 MHz





of Restarts_Uplink_698 - 716 MHz



of Restarts_Uplink_824 - 849 MHz

