

ShenZhen SolidRF Communications Co., Ltd

Nov. 08, 2021

Subject: Tuning and Adjustment of Signal booster, FCC ID: A7V-SR14652002

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Yu Chi

A handwritten signature in cursive script, appearing to read 'chiqu', is positioned below the printed name 'Yu Chi'.