



Craig D. Bohren
Hardware Development
Phone: (214) 567 2505
Fax: (214) 567 2492
Email: c-bohren1@ti.com


Texas Instruments, Inc.
RFID Systems Group
6550 Chase Oaks Blvd.
M/S 8470
Plano, Texas 75023-3048

Subject: FCC Label Placement on S4110 MFR S4100 Evaluation Kit Readers

- 1) Boxed S4110 MFR Evaluation Kit Reader
- 2) SDK S4110 MFR Evaluation Kit Reader

Date: 16 March 2004

I FCC Label



II FCC Label placement on Boxed S4110 MFR Evaluation Kit Reader




Figure 1: FCC Label placement on Boxed S4110 MFR Evaluation Kit Reader



Figure 2: Boxed S4110 MFR Evaluation Kit Reader

III Placement of FCC Label on SDK S4110 MFR Evaluation Kit Reader



Figure 3: SDK S4110 Evaluation Kit Reader



Figure 4: FCC Label on SDK S4110 MFR Evaluation Kit Reader



Figure 5: Label Placement on SDK S4110 MFR Evaluation Kit Reader