


RX unit – housing removed – PCB front side



Shield cover for the audio switching amp removed






Location of the radio module



ML5800 radio module (cover removed)



radio control module and partial backside of ML5800 radio module.

