



11/16/2006

To: Curtis-Straus LLC TCB
527 Great Rd
Littleton, MA 02702

Re: Class 2 change request

Gentlemen:

This letter is to comply with 47 CFR 2.1043(b)(2) of the rules for Class II Permissive change to our equipment with the FCC ID below. Test data demonstrating compliance of the modified equipment is detailed in this filing.

FCC ID: A94YZUT and A94YZUR

Description of changes:

1. Change of firmware resulting in an internal clock frequency change from 12.288 MHz to 6.144 MHz
2. Change coax lead length of the master unit (A94YZUT) from approximately 4.5" to 1.5"
3. Removal of the extra grounding solder points on the shield of the radio transceiver board (A94YZUR)

Sincerely,

A handwritten signature in black ink, appearing to read "Peter Boers", written over a large, loopy circular flourish.

Peter Boers
DCE
Bose Corporation