

Please supply photos of the SL2 receiver power supply cable as test report mentions molded ferrites being used on them.

Attached is the requested photo. Please be aware that we do not need these ferrite beads for compliance to FCC Part 15B limits. This product is intended for use next to our FM receivers and we needed extra suppression so we did not interfere with the FM receiver itself.