ITS Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901180
Mode: Charging

Tested By:Hong, Report No.:9901180
Scan Settings (1 Range)
|-------- Frequencies --------||------- Receiver Settings -------|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO LN	OFF	60dB

Transducer	No.	Start	Stop	Name
	3	9k	30M	EI078

Final Measurement: x QP
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

Report No.: 9901180
Mode: Charging

Tested By:Hong, Report No.:9901180
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
18.16500	28.2	48.0
25.43000	37.8	48.0

' limit exceeded

Ctrl. No.: N/A

ITS Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901180
Mode: Standby

Tested By:Hong, Report No.:[illegible]
Scan Settings 1 Range
Frequencies Receiver Settings

Start	Stop	Step	IF BW	Detector	M-Tim	Atten	Preamp	OpEge
[illegible]	[illegible]	[illegible]	[illegible]	PK	[illegible]	AUTO	LN OFF	60dB

Final Measurement: [illegible]
Meas Time: [illegible]
Subranges: 16
Acc Margin: 29dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl. No.: N/A

Report No.: 9901180
Mode: Standby

Tested By:Hong, Report No.:9901180
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
25.43000	37.5	48.0

* limit exceeded

Ctrl. No.: N/A

Report No.: 9901180
Mode: Transmission

Tested By:Hong, Report No.:9901180
Scan Settings (1 Range)
Frequencies — Receiver Settings

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	10ms	AUTO LN	OFF	60dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Final Measurement: x QP
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



Ctrl. No.: N/A

Report No.: 990180
Mode: Transmission

Tested By:Hong, Report No.:9901180
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
18.16500	28.7	48.0
25.43000	36.6	48.0

' limit exceeded

Ctrl. No.: N/A