

Report No.: 9900778

Tested By: Hong, Report No.: 9900778

Scan Settings (1 Range)

Frequency			Receiver Settings		
Start	Stop	Sweep	IF BW	Detector	Hi-Time
450K	30M	OE	10K	PK	30ms AUTO LN OFF

Transducer No.	Start	Stop	Name
3	9K	30M	EI078

Final Measurement: X QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

dBuV

80

70

60

50


40

30

20

10

0



FCC15B

30
MHz

PAGE 1

Ctrl. No.: N/A

Report No.: 9900778

Tested By: Hong, Report No.: 9900778

Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB	

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.45000	22.0	48.0
16.62000	28.4	48.0

* limit exceeded

Ctrl. No.: N/A

FCCID: AAO4300494T