



Intertek Testing Services ETL SEMKO

Mode = Tx

Report No.: 9912828

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

Frequencies			Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten
450k	30M	5k	10k	PK	20ms	AUTO
				LN	OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl No.: N/A

Mode = Tx



Intertek Testing Services

ETL SEMKO

Report No.: 9912828

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

no Results

Ctrl No.: N/A



Intertek Testing Services ETL SEMKO

Report No.: 9912828

Mode = Charging

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Mode = Charging

Report No.: 9912828

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB	

Final Measurement Results:

no Results

Ctrl No.: N/A



Intertek Testing Services ETL SEMKO

Mode = Stand by

Report No.: 9912828

Tested By: Hong, Report No.: 9912828


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Mode = Stand by

Report No.: 9912828

Tested By: Hong, Report No.: 9912828

Scan Settings (1 Range)

----- Frequencies ----- || ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

no Results

Ctrl No.: N/A