



Intertek Testing Services

ETL SEMKO

Report No.: 0009820

Mode: Talk Mode

Tested By: Hong, Report No.: 0009820


Scan Settings (1 Range)

Frequencies			Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten
450k	30M	5k	10k	PK	20ms	AUTO LN OFF

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0009820

Mode= Talk Mode

Tested By: Hong, Report No.: 0009820

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

3.59000 33.2 48.0

* limit exceeded

Ctrl No.: N/A