



Class II Permissive Change Certification Application - Additional Information

Aug 24, 2004

American Telecommunications Certification Body, Inc.
6731 Whittier Avenue
Suite C110
McLean, VA 22101

RE : Class II Permissive Change Certification Application
FCC Tx ID : AB6NT800MFRM
IC ID: 332292158

Dear Sir/Madam

This letter is to respond the additional information that requested by ATCB. The answers to your concerns are listed below:

Concern# 1) Please note that the document explaining the reason for the PC2 does not make it clear if there were any hardware changes from the original involved in this PC. Please explain if any hardware changes were done and what they were if done.


Response: There is no extra hardware change in the radio required to support 1xEV-DO, IS856 carrier. The "Certification Application.pdf" has been updated to include the missing information and the document has been submitted to the ATCB web site under "Additional Information".

Concern# 2) Please note that the IC number on several documents do not exactly match the IC number on the RSP100. The RSP100 form shows 332-292158 while other documentation shows 332292158. Please explain.

Response: The "332" is Nortel Networks' "Company Code" provided by IC. The "292158" was provided by IC at the completion of the original application. I have checked the IC's REL database and the certification number is "332292158"; therefore, all the application documents have been followed the REL database. However, when I filled out the RSP100 form, the form forced me to put a "-" in between "332" and "292158".

Please contact me for further information if necessary.

Sincerely,


Signature

Thomas Wong,
Regulatory Prime
Wireless Division, Nortel Networks
Tel: 403-769-2425 Fax: 403-769-7806
Email: thomaswg@nortelnetworks.com