

July 10, 1998

Re: Class II Change (Re-assessment) for
GM Security Receiver

FCC ID: ~~AB00323R~~ *AB0 0232R* *WAB*
CANADA: 218 102 884

LIST OF PHOTOGRAPHS

	<u>Page</u>
List of photographs	1 of 2
Receiver topside	
Receiver bottomside	2 of 2

EXHIBIT I

Page 1 of 2

U of Mich file 415031-944

