APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1



Photo 2

Worst Case Position

ECU
Below 30 MHz
X-axis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis

X-axis

Y-axis

Z-axis

Immobilizer
Below 30 MHz
Zaxis
Above 30 MHz
Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



UL Japan, Inc.
Ise EMC Lab.
4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN
Telephone : +81 596 24 8999
Facsimile : +81 596 24 8124

Worst Case Position



With key



Without key (Worst)

End of Report