



APPENDIX 1: Photographs of test setup

Conducted Emission **Base Unit and Hand unit** **Front**



Side




Spurious Emission (Radiated)

Hand unit

Front



Rear



UL Apex Co., Ltd.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124

MF060b(14.06.06)

Worst Case Position (Horizontal: Y-axis/ Vertical:Z-axis)

Hand unit

X-axis



Y-axis



Z-axis



UL Apex Co., Ltd.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116


Facsimile : +81 596 24 8124

MF060b(14.06.06)


Radiated Emission

Base Unit

Front



Rear



UL Apex Co., Ltd.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124

MF060b(14.06.06)