

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Worst Case Position


Module (Horizontal: X-axis / Vertical:X-axis)

Antenna (Horizontal: Y-axis / Vertical:X-axis)


Module X-axis



Antenna X-axis




Module Y-axis



Antenna Y-axis



Module Z-axis



Antenna Z-axis



End of Report