

APPENDIX 3: Photographs of test setup

Conducted tests (Antenna terminal)



Photo 1



Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission
(Below 1 GHz)




Photo 1




Photo 2

Radiated Spurious Emission
(Above 1 GHz)




Photo 1




Photo 2

Worst Case Position


Below 1 GHz: (Horizontal: X-axis/ Vertical: X-axis)

Above 1 GHz: (Horizontal: X-axis/ Vertical: X-axis)

X-axis



Y-axis



Z-axis



Frequency stability



End of Report