









DIR





DIP
CHECKER
8F012-IB
KPC 1694V-0
PFUP1248ZA
2001.3.9



PFUP1248ZA



CN510
DIP
PFUP1246ZA 2001.03.09
BAT501
R603
IC508
IC512
IC503
J502
CN606
CN505
CN603
CN604
AUDIO CH
MODEL
VIDEO
REF CH
VOICE



PFUP1246ZA
2001.03.09



MITSUMI ELEC.CO.,LTD.
758 13
SECONDARY
PRIMARY
RISK OF FIRE. REPLACE ONLY WITH
SAME TYPE AND RATINGS
OF FUSE. (F101)
FOR CONTINUED PROTECTION AGAINST
CAUTION
SRF1196UC
12SV 5A


68-XXXX-89
125V 5A
PRIMARY
SECONDARY




DIP




PFUP1245ZA 2001.5.5

