




IMPORTANT SAFETY NOTICE: POTENTIALS ABOVE 120V IS PRESENT ON THE PARTS AND WIRING IN SECONDARY CIRCUIT OF HIGH VOLTAGE TRANSFORMER. WHEN OVEN IS ENERGIZED. EXTREMELY CARE SHOULD BE TAKEN DURING REPAIR.