



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 21, 2004

RE: General Instrument

FCC ID: ACQWA840GV2

I have a few comments on this Application.

- 1.) The Block Diagram does not meet the requirements of 2.1033(b)(5). Please revise. In general, the Commission is concerned with the Block Diagram of the RF signal generation section of any device and not any associated digital circuitry. Please provide a listing of all oscillators and all RF signal paths including clock and IF frequencies.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.