



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 28, 2003

RE: Motorola

FCC ID: ACQWN825G

I have a few comments on this Application.

- 1.) I believe the RF power has a typographical error on page 4 of the SAR Report.
- 2.) The SAR Report makes several references to average SAR values when what is required is peak SAR. Please review and correct.
- 3.) The peak field strength shown for the fundamental does not seem to match what I would expect if I converted your approximate +17dBm EIRP (+16dBm conducted with a 1dBi antenna) on a three meter site. Do you have an explanation?

William H. Graff
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.