

*NOTE1. Wire color code. (B):large wires.
2. Shield should be effectively grounded at scanner unit.
3. Connector plug factory-wired.
4. Shield grounded thru connector case.

REV No.	MARK	DATE	REMARKS	REV-BY	APPRV
	△x				
	△x				
	△x				
	△x				
	△x				

MDL	FR-7062	CODE No.		SHEET No.	1/1
		ITEM No.			

APPRV	CHCKD	DSIGND	DRAWN	TIT-LE	INTERCONNECTION DIAGRAM
		97,10,17 北野	97,10,17 北野	DWG No.	03-142-6001-0

FURUNO ELECTRIC CO.,LTD.