



Icom Inc.

1-1-32, Kamiminami, Hirano-ku, Osaka, 547-0003 Japan

Phone : 06 6793 5302 Fax : 06 6793 0013

E-Mail: export@icom.co.jp

August 27, 2003

Federal Communications Commission
Authorization & Evaluation Division
7435 Oakland Mills Road
Colombia, Maryland 21046

RE: Blocked Frequency
FCC ID: AFJ236801

Dear Sir/ Madam

The frequencies 400-406.1MHz are blocked to the AFJ236801 user by the radio cloning software. Because the radio does not have a continuous tuning mode (VFO), it can only be used on channel programmed with the cloning software. Only the manufacture and authorized dealers have this software. Therefore it is not possible for the user to operate in this frequency region.

Thank you for your attention to this matter.

Sincerely

Icom Incorporated

A handwritten signature in black ink, consisting of three characters: '青' (Aoki), '木' (Takashi), and '斎' (Aoki).

Takashi Aoki

General Manager