

To: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>
Subject: Reply to ATCB Cooments_081103, FCC ID: AFJ236801

"urn:schemas-microsoft-com:office:office" xmlns:w = "urn:schemas-microsoft-com:office:word">

Hi Timothy,

Attached please find the followings:

- (1) Revised test report with additonal Emission Masks tests wiht the scrambler
- (2) Reply to your questions
- (3) External photos
- (4) Icom's statement for compliance with FCC 90.203(e)&(g)

Please feel free to contact us, if you have any queries.

Best Regards,

Tri M. Luu, P.Eng.
Ultratech Engineering Labs Inc.
3000 Bristol Circle
Oakville, Ontario
Canada L6H 6G4

Tel.: 905-829-1570
Fax.: 905-829-8050
Email: tri@ultratech-labs.com
Web site : www.ultratech-labs.com

31040/SIT

C-1376

46390-2049

200093-0

SL2-IN-E-1119R

00-034



[IC-FR40001-FCC90 Test Report1.pdf](#)



[ATCB - CORRES0811031.pdf](#)



[FR40001-xphotos1.pdf](#)



[FR40001-Part90.203e_f1.pdf](#)



[ATCB Comments_0811031.pdf](#)