

SONY

Sony EMCS Corporation

1, Suzumegairi, Sakazaki, Kohda-cho, Nukata-gun, Aichi-ken., 444-0194 Japan

■ Main Office TEL: +81-564-63-6166 FAX: +81-564-63-6179

□ Shinagawa Branch TEL: +81-3-5769-5643 FAX +81-3-5769-5963

Letter of Specifying the Changes

Date: October 3, 2002

American Telecommunications Certification Body, Inc.

6731 Whittier Avenue

Suite C110

McLean, VA 22101

RE: Specifying the Change under FCC section 2.1043 (Class II Permissive Change)

FCC ID: AK8DCRIP220

This is a request of changes in certified product under section 2.1043 (Class II Permissive Change) (b) (2) for Digital Video Camera Recorder (model: DCRIP220) which has been already granted as FCC ID: AK8DCRIP220.

Changes:

1. Version change of LSI on Bluetooth module in BT-012 board
2. Value of two capacitors on BT-012 board changes

According to the detail explanation for the above changing points and test report to the changed model, we would like you to confirm the attached documents.

Radiated emission test and conducted emission test were performed since performance degradation may happen for these test items.

Except above mentioned changes, changed equipment is completely same with the one which has already been granted by the FCC as FCC ID: AK8DCRIP220.

It is verified and confirmed that the equipment still comply with the FCC requirement after changes.

Thank you for your attention to this matter.



Hirofumi Tsutsui

Manager, Product Safety

DI Engineering Center

Sony EMCS Corporation

TEL: +81-564-63-6166

FAX: +81-564-63-6179