

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Emission
(Below 30 MHz)




Photo 1




Photo 2

Radiated Emission



Photo 1



Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

Below 30 MHz	Z-axis
Above 30 MHz	Horizontal: X-axis / Vertical: Z-axis

X-axis



Y-axis



Z-axis



MODE


Battery power Supply



USB power Supply (Worst)



MI-Shoe power Supply



With/Without Tag



With Tag (2nd harmonic: Worst)



Without Tag (Other than 2nd harmonic: Worst)

UL Japan, Inc.


Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Frequency Tolerance



Photo

End of Report