









































Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.

No. 491, Zhongfu Rd., Linkou Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303



A.5 FREQUENCY STABILITY

Test Date	2026/09/09	Temp./Hum.	22°C/55%
Test Voltage	120Vac / 102Vac / 138Vac	Tested By	Sean Wang

A.5.1 Frequency stability Result


Temperature (°C)	Voltage (Vac)	Centre Frequency (MHz)	Measurement Value (MHz)	Frequency Stability (ppm)
25	120	5180	5180.004	0.772
-30	102	5180	5180.03	5.792
	138	5180	5180.013	2.510
-20	102	5180	5180	0.000
	138	5180	5180.018	3.475
-10	102	5180	5179.995	-0.965
	138	5180	5179.998	-0.386
0	102	5180	5180.011	2.124
	138	5180	5180.009	1.737
10	102	5180	5180.006	1.158
	138	5180	5179.992	-1.544
20	102	5180	5179.993	-1.351
	138	5180	5179.986	-2.703
30	102	5180	5180.02	3.861
	138	5180	5180.012	2.317
40	102	5180	5180.028	5.405
	138	5180	5180.004	0.772
50	102	5180	5179.981	-3.668
	138	5180	5179.991	-1.737

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


A.6 BAND EDGE

Test Date	2026/07/07	Temp./Hum.	24°C /62%
Cable Loss	0.80dB	Tested By	Sean Wang
Test Voltage	DC 3.8V (Via Battery)		




Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303



Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303





Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City 244, Taiwan

APPENDIX B

Tel: +886 2 26099301
Fax: +886 2 26099303

APPENDIX B

TEST PHOTOGRAPHS

(Model: YY1304B)