


APPENDIX 3: Photographs of test setup

Radiated Spurious Emission (Below 1 GHz)



UL Japan, Inc.



Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone: +81-478-82-0963

Facsimile: +81-478-82-3373

Radiated Spurious Emission (Above 1 GHz)



Worst Case Position (Horizontal: Y-axis/ Vertical:Y-axis)

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone: +81-478-82-0963

Facsimile: +81-478-82-3373