

Uniden America Corporation
3001 Gateway Dr.
Suite 130
Irving, TX 75063
817-858-3300
Fax: 817-858-3333



May 29, 2018

To: Federal Communications Commission
Equipment Authorization Branch
Laboratory Division
Office of Engineering and Technology
7435 Oakland Mills Road
Columbia, Maryland 21046

Subject: Attestation statement regarding the WARNING: MODIFICATION label located inside the battery compartment

Applicant: Uniden America Corporation
3001 Gateway Drive, Suite 130,
Irving, TX 75063
Paul Roby – Quality Assurance and Regulatory Manager

TYPE OF EQUIPMENT: Digital Scanning Receiver
FCC IDENTIFIER: AMWUB383

Dear Sir or Madam:

I attest that the SDS100 Battery Pack will be shipped in the packaging separately from the receiver and must be installed prior to scanner operations. The "WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR RADIOTELEPHONE SERVICE IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW" is visible to the consumer prior to installation of the battery pack. The before mentioned WARNING statement is also located in the Owner's Manual, Page 2.

There is no adequate location on the exterior of the product where the label would last the life of the product and therefore would not be a practical location.

Please contact the undersigned if you have any questions or need any further information.

Regards,

A handwritten signature in black ink, appearing to read "Paul Roby".

Paul Roby
Quality Assurance and Regulatory Manager